

Aviation Investigation Final Report

Location:	PIERRE, South Dakot	a	Accident Number:	DEN83LA159
Date & Time:	July 2, 1983, 18:00 L	ocal	Registration:	N8965G
Aircraft:	CESSNA	188B	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General avia	ition - Personal		

Analysis

THE PLT WAS MAKING PRACTICE SWATH RUNS WITH A LOAD OF WATER. DURING THE THIRD TURN, AT ABOUT 100 FT AGL, THE ENG STOPPED, ACCORDING TO THE PLT. THE ACFT THEN LANDED HARD & CARTWHEELED. NO ENG MALFUNCTIONS WERE FOUND.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: MANEUVERING

Findings
1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: FORCED LANDING Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Factual Information

Pilot Information

Certificate:	Commercial	Age:	29,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 19, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	343 hours (Total, all aircraft), 40 hours (Total, this make and model), 293 hours (Pilot In Command, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N8965G
Model/Series:	188B 188B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	18801333T
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	April 10, 1983 100 hour	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1945 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	IO-520-D
Registered Owner:	GERALD EDWARD OGAN	Rated Power:	285 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PIR	Distance from Accident Site:	
Observation Time:	17:00 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 8000 ft AGL	Visibility	45 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	14 knots /	Turbulence Type Forecast/Actual:	1
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	30°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	PIERRE , SD (PIR)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	17:30 Local	Type of Airspace:	Class G

Airport Information

Airport:	Runway Surface Type:	Grass/turf
Airport Elevation:	Runway Surface Condition:	Dry
Runway Used: 0	IFR Approach:	None
Runway Length/Width:	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.369369,-100.319046(est)

Administrative Information

Investigator In Charge (IIC):	Tranter, Verlin
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=16109

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.