

Aviation Investigation Final Report

Location:	ENGLEWOOD, Cold	orado	Accident Number:	DEN84LA160
Date & Time:	May 22, 1984, 15:1	0 Local	Registration:	N42984
Aircraft:	PIPER	PA-34-220T	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General av	viation		

Analysis

ACCORDING TO THE PLT, THE ACFT TOUCHED DOWN DURING A LANDING, THEN BECAME AIRBORNE AGAIN IN UNFAVORABLE WIND CONDITIONS. HE REPORTED THAT THE PLANE THEN SLAMMED BACK ONTO THE RWY & WAS DAMAGED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING Phase of Operation: LANDING

Findings

1. (F) WEATHER CONDITION - UNFAVORABLE WIND

- 2. (C) COMPENSATION FOR WIND CONDITIONS IMPROPER PILOT IN COMMAND
- 3. (C) REMEDIAL ACTION INADEQUATE PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Commercial	Age:	48,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 21, 1983
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1477 hours (Total, all aircraft), 113 hours (Total, this make and model), 1305 hours (Pilot In Command, all aircraft), 29 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N42984
Model/Series:	PA-34-220T PA-34-220T	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	34-8333071
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	March 24, 1984 Annual	Certified Max Gross Wt.:	4750 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	195 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	TSIO-360-KB
Registered Owner:	DONALD WHITE	Rated Power:	220 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	APA ,5872 ft msl	Distance from Accident Site:	
Observation Time:	14:45 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Unknown / 9000 ft AGL	Visibility	50 miles
Lowest Ceiling:	Broken / 9000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	12 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	80°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	19°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	ASPEN , CO (ASE)	Type of Flight Plan Filed:	IFR
Destination:		Type of Clearance:	IFR
Departure Time:	14:20 Local	Type of Airspace:	Class D

Airport Information

Airport:	ARAPAHOE COUNTY APA	Runway Surface Type:	Asphalt
Airport Elevation:	5872 ft msl	Runway Surface Condition:	Dry
Runway Used:	34R	IFR Approach:	None
Runway Length/Width:	8500 ft / 101 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.639282,-104.989082(est)

Administrative Information

Investigator In Charge (IIC):	Winningham, Fred
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=16386

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.