

Aviation Investigation Final Report

Location:	LUSTRE, Montana		Accident Number:	DEN84LA182
Date & Time:	June 16, 1984, 14:45	Local	Registration:	N9311T
Aircraft:	CESSNA	180C	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General avia	ition - Personal		

Analysis

DUE TO STRONG CROSSWIND CONDITIONS AT THE PREPARED LANDING STRIP, THE PILOT ELECTED TO LAND IN AN OPEN FIELD. ON TOUCHDOWN, THE RIGHT MAIN LANDING GEAR ENCOUNTERED A HOLE, BREAKING THE MOUNTING STRUCTURE AND COLLAPSING THE GEAR. A GROUND LOOP ENSUED. THE PILOT STATED AVOIDANCE OF UNKNOWN, UNIMPROVED LANDING AREAS WOULD PREVENT SUCH MISHAPS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: MAIN GEAR COLLAPSED Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. LANDING GEAR, MAIN GEAR - OVERLOAD

- 2. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA SELECTED PILOT IN COMMAND
- 3. GROUND LOOP/SWERVE
- 4. (F) WEATHER CONDITION UNFAVORABLE WIND

Factual Information

Pilot Information

T not information			
Certificate:	Commercial	Age:	38,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 1, 1984
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	669 hours (Total, all aircraft), 446 hours (Total, this make and model), 60 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N9311T
Model/Series:	180C 180C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	50811
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	August 8, 1983 Annual	Certified Max Gross Wt.:	2650 lbs
Time Since Last Inspection:	92 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4800 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	0-470-L
Registered Owner:	DONALD D. KIRK	Rated Power:	230 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	40 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	18 knots / 25 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	27°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:35 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	Precautionary landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	48.280319,-106.060943(est)

Administrative Information

Investigator In Charge (IIC):	Mucho, Gary
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=16403

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.