



Aviation Investigation Final Report

Location: TAYLOR, Utah Accident Number: DEN85LA047

Date & Time: December 22, 1984, 15:15 Local Registration: N3648A

Aircraft: PIPER PA-22-135 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

ACFT COLLIDED WITH A PILE OF SNOW NEAR THE EDGE OF RWY WHILE LANDING. PLT STATED HE MISJUDGED THE APCH AND REDUCED POWER PREMATURELY.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: UNDERSHOOT

Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings

- 1. (C) IN-FLIGHT PLANNING/DECISION POOR PILOT IN COMMAND
- 2. (C) JUDGMENT POOR PILOT IN COMMAND
- 3. (F) THROTTLE/POWER CONTROL INADEQUATE PILOT IN COMMAND
- 4. (F) AIRSPEED IMPROPER PILOT IN COMMAND
- 5. (F) PROPER GLIDEPATH NOT MAINTAINED PILOT IN COMMAND
- 6. (C) PROPER TOUCHDOWN POINT NOT OBTAINED PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings
7. TERRAIN CONDITION - SNOWBANK

Occurrence #3: NOSE OVER Phase of Operation: LANDING

DEN85LA047 Page 2 of 5

Factual Information

Pilot Information

Certificate:	Private	Age:	30,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Expired	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	255 hours (Total, all aircraft), 255 hours (Total, this make and model), 212 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N3648A
Model/Series:	PA-22-135 PA-22-135	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	22-1908
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	June 29, 1978 Annual	Certified Max Gross Wt.:	1850 lbs
Time Since Last Inspection:	149 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2674 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	0-290-D2
Registered Owner:	KENNETH BOYDSTON	Rated Power:	135 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 DEN85LA047

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-1°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:45 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Dirt
Airport Elevation:	4400 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	1000 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 4 of 5 DEN85LA047

Administrative Information

Investigator In Charge (IIC):	Feith, Gregory
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=16613

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN85LA047