



# **Aviation Investigation Final Report**

Location: RIVERTON, Wyoming Accident Number: DEN85LA154

Date & Time: June 7, 1985, 07:00 Local Registration: N8280H

Aircraft: CALLAIR A-9 Aircraft Damage: Substantial

**Defining Event:** 1 Minor

Flight Conducted Under: Part 137: Agricultural

### **Analysis**

DURING AN AERIAL APPLICATION TURN-AROUND MANEUVER, THE ENG LOST POWER. THE PLT STATED THAT HE IMMEDIATELY CHANGED THE FUEL SELECTOR & TURNED ON THE BOOST PUMP, BUT THE ACFT WAS TOO LOW FOR THE ENG TO HAVE TIME TO RESTORE POWER. THE ENG HAD BEEN USING FUEL FROM A TANK THAT WAS LOW ON FUEL. NO FAA PLT CERTIFICATE WAS FOUND OR REPORTED.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: MANEUVERING - AERIAL APPLICATION

#### **Findings**

- 1. PROCEDURES/DIRECTIVES NOT FOLLOWED PILOT IN COMMAND
- 2. QUALIFICATION PILOT IN COMMAND
- 3. (F) FLUID, FUEL LOW LEVEL
- 4. MANEUVER PERFORMED PILOT IN COMMAND
- 5. (C) FLUID, FUEL STARVATION
- 6. (C) FUEL SYSTEM IMPROPER USE OF PILOT IN COMMAND

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Findings

7. EMERGENCY PROCEDURE - INITIATED

-----

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING

Page 2 of 5 DEN85LA154

# **Factual Information**

### **Pilot Information**

Certificate:	None	Age:	Male
Airplane Rating(s):	None	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:			

### **Aircraft and Owner/Operator Information**

Aircraft Make:	CALLAIR	Registration:	N8280H
Model/Series:	A-9 A-9	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2350 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	O-540
Registered Owner:	JENNETTE PATENAUDE	Rated Power:	230 Horsepower
Operator:	RED LODGE AIRWAYS	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 DEN85LA154

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	RIW ,5500 ft msl	Distance from Accident Site:	
Observation Time:	06:45 Local	Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Unknown	Visibility	40 miles
Lowest Ceiling:	Broken / 15000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	19°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

## **Airport Information**

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Forced landing

## Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	43.029003,-108.409126(est)

Page 4 of 5 DEN85LA154

#### **Administrative Information**

Investigator In Charge (IIC):	Winterowed, Fred
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=16694

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN85LA154