



Aviation Investigation Final Report

Location: ALBUQUERQUE, New Mexico Accident Number: DEN89LA013

Date & Time: October 9, 1988, 11:31 Local Registration: N3592C

Aircraft: Raven S-60A Aircraft Damage: Substantial

Defining Event: 1 Minor, 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT, WITH TWO PAX ABOARD A HOT AIR BALLOON, PARTICIPATED IN THE 1988 ALBUQUERQUE, NM INTERNATIONAL BALLOON FIESTA. THE PLT SAID HE RECEIVED A WX BRIEFING AND THEN DEPARTED IN VFR WX CONDITIONS. AFTER APRX 45 MIN OF FLT, THE PLT SAID HE ENCOUNTERED UNPREDICTED ADVERSE WINDS. THE BALLOON BEGAN AN UNCONTROLLED DESCENT. HE SAID HE HIT THE GROUND SEVERAL TIME BEFORE COMING TO A STOP.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT ENCOUNTER WITH WEATHER

Phase of Operation: CRUISE

Findings

1. (C) WEATHER CONDITION - DOWNDRAFT

2. (C) WEATHER CONDITION - UNFAVORABLE WIND

3. (C) WEATHER EVALUATION - INADEQUATE - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: DESCENT - UNCONTROLLED

Page 2 of 5 **DEN89LA013**

Factual Information

Pilot Information

Certificate:	Commercial	Age:	53,Male
Airplane Rating(s):	None	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Balloon	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	266 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Raven	Registration:	N3592C
Model/Series:	S-60A S-60A	Aircraft Category:	Balloon
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	S60A-3098
Landing Gear Type:	Hull	Seats:	
Date/Type of Last Inspection:	September 8, 1988 Annual	Certified Max Gross Wt.:	1600 lbs
Time Since Last Inspection:	20 Hrs	Engines:	Unknown
Airframe Total Time:		Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	CIRCUS CIRCUS HOTEL	Rated Power:	
Operator:	CIRCUS CIRCUS HOTEL	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 DEN89LA013

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	15 miles
Lowest Ceiling:	Broken / 12000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	4 knots / 6 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	21°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	ALBUQUERQUE, NM (NONE)	Type of Flight Plan Filed:	None
Destination:	(NONE)	Type of Clearance:	None
Departure Time:	10:45 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Dirt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 2 None	Latitude, Longitude:	

Page 4 of 5 DEN89LA013

Administrative Information

Investigator In Charge (IIC): Tranter, Verlin

Additional Participating Persons: DALE HORNER; ALBUQUERQUE, NM

Original Publish Date: September 11, 1989

Last Revision Date:
Investigation Class: Class

Note:
Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=17628

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN89LA013