



Aviation Investigation Final Report

Location: HASKELL, Oklahoma Accident Number: FTW92LA182

Date & Time: July 18, 1992, 17:00 Local **Registration:** N1342

Aircraft: SCHLEICHER KA6E Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

DURING AN AIR TOW TAKEOFF THE RIGHT WING RUNNER WAS UNABLE TO KEEP UP WITH THE GLIDER AND LET GO OF THE WING. THE RIGHT WING DROPPED AND THE GLIDER VEERED RIGHT OFF OF THE RUNWAY AND STRUCK A BALE OF HAY, DAMAGING THE RIGHT WING. THE PILOT RELEASED THE TOW AFTER THE COLLISION.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN DIRECTIONAL CONTROL AND THE WING RUNNERS FAILURE TO KEEP THE RIGHT WING UP.

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. OBJECT - OTHER

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. (C) PROPER ASSISTANCE - NOT PERFORMED - GROUND PERSONNEL

Factual Information

Pilot Information

Certificate:	Commercial	Age:	60,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 13, 1991
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	3325 hours (Total, all aircraft), 19 hours (Total, this make and model), 3200 hours (Pilot In Command, all aircraft), 48 hours (Last 90 days, all aircraft), 21 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	SCHLEICHER	Registration:	N1342
Model/Series:	KA6E KA6E	Aircraft Category:	Glider
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	4135
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	June 9, 1992 Annual	Certified Max Gross Wt.:	660 lbs
Time Since Last Inspection:		Engines:	0 Unknown
Airframe Total Time:	565 Hrs	Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	HARRIS, GERALD R.	Rated Power:	
Operator:	HARRIS, GERALD R.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 FTW92LA182

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 4000 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	32°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	17:00 Local	Type of Airspace:	Class D

Airport Information

Airport:	HASKELL MUNI 00K7	Runway Surface Type:	Asphalt
Airport Elevation:	588 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	3710 ft / 50 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	35.82088,-95.670417(est)

Page 3 of 4 FTW92LA182

Administrative Information

Investigator In Charge (IIC):	Wandel, Warren	
Additional Participating Persons:	EDWARD C NOWE; OKLAHOMA CITY, OK	
Original Publish Date:	June 30, 1993	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=18534	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 FTW92LA182