



Aviation Investigation Final Report

Location: PLAIN DEALING, Louisiana Accident Number: FTW83LA381

Date & Time: August 15, 1983, 08:00 Local Registration: N53282

Aircraft: CESSNA A188B Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

THE PLT FLEW FROM HIS HOME BASE TO PLAIN DEALING, LA TO ONLOAD MATERIAL FOR AERIAL APPLICATION. DURING THE LANDING ROLL-OUT, THE RIGHT MAIN GEAR LEG FAILED. A METALLURGICAL EXAM REVEALED THE GEAR LEG FAILED FROM FATIGUE WHICH WAS INITIATED BY CORROSION PITS IN A RUSTED AREA.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

1. (C) LANDING GEAR, MAIN GEAR - CORRODED 2. (C) LANDING GEAR, MAIN GEAR - FATIGUE

Factual Information

Pilot Information

Certificate:	Commercial	Age:	43,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	February 3, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	6000 hours (Total, all aircraft), 3000 hours (Total, this make and model), 300 hours (Last 90 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N53282
Model/Series:	A188B A188B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	188017331
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	February 21, 1983 Annual	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Not installed	Engine Model/Series:	10-520
Registered Owner:	ARK LA AG. FLYING SERVICE INC.	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 FTW83LA381

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VM	C)	Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:			Direction from Accident Site:	
Lowest Cloud Condition:	Clear		Visibility	10 miles
Lowest Ceiling:	None		Visibility (RVR):	
Wind Speed/Gusts:	5 knots /		Turbulence Type Forecast/Actual:	/
Wind Direction:	135°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:			Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscura	ation; No Precipita	ation	
Departure Point:	BRADLEY	, AR (PVT)	Type of Flight Plan Filed:	None
Destination:			Type of Clearance:	None
Departure Time:	07:55 Loca	I	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Dirt
Airport Elevation:	250 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	32.899375,-93.690093(est)

Page 3 of 4 FTW83LA381

Administrative Information

Investigator In Charge (IIC):	Johnson, J.
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=21015

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 FTW83LA381