



Aviation Investigation Final Report

Location: ALBUQUERQUE, New Mexico Accident Number: FTW84LA087

Date & Time: December 3, 1983, 10:20 Local Registration: N4061P

Aircraft: BALLOON WORKS FIREFLY 7 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT REPORTED THAT DURING FLT, UNFAVORABLE WINDS WERE ENCOUNTERED. AN APCH WAS MADE TO A GOLF COURSE, BUT THE PLT ABORTED DUR TO HIGH WINDS. A SHORT TIME LATER, AN APCH WAS MADE TO A PARK AREA. ACCORDING TO THE PLT, THE WIND SWITCHED AS THE BALLOON TOUCHED DOWN & BLEW THE ENVELOPE INTO TREES. A SAFETY LINE HAD BEEN DROPPED TO WAITING GROUND CREW PERSONNEL, BUT THE WIND WAS TOO STRONG FOR THEM TO CONTROL THE ENVELOPE'S MOVEMENT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) PLANNING/DECISION - IMPROPER - PILOT IN COMMAND

2. (F) WEATHER CONDITION - UNFAVORABLE WIND

3. (F) OBJECT - TREE(S)

Page 2 of 5 FTW84LA087

Factual Information

Pilot Information

Certificate:	Commercial	Age:	40,Female
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Balloon	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	114 hours (Total, all aircraft), 114 hours (Total, this make and model), 13 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BALLOON WORKS	Registration:	N4061P
Model/Series:	FIREFLY 7 FIREFLY 7	Aircraft Category:	Balloon
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	7981
Landing Gear Type:	Tricycle	Seats:	
Date/Type of Last Inspection:	December 13, 1982 Annual	Certified Max Gross Wt.:	900 lbs
Time Since Last Inspection:	31 Hrs	Engines:	Unknown
Airframe Total Time:	182 Hrs	Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	LINDA L. DOHERTY	Rated Power:	
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 FTW84LA087

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	20 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	6°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	ALBUQUERQUE , NM	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	08:35 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Grass/turf
Airport Elevation:	5300 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	35.140331,-106.490455(est)

Page 4 of 5 FTW84LA087

Administrative Information

Investigator In Charge (IIC):	Mcfall, T.
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=21225

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 FTW84LA087