



Aviation Investigation Final Report

Location: SAN ANTONIO, Texas Accident Number: FTW85LA082

Date & Time: December 21, 1984, 17:30 Local Registration: N48252

Aircraft: FAIRCHILD M-62A Aircraft Damage: Substantial

Defining Event: 1 Serious

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

A TOTAL PWR LOSS WAS EXPERIENCED WHILE MANUEVERING OVER AN AIRPORT AT ABOUT 250 FT AGL. THE ACFT COLLIDED WITH ROUGH TERRAIN DURING THE FORCED LANDING. VISUAL INSPECTION OF THE ACFT FUEL SYSTEM INDICATED THAT THE PWR LOSS WAS DUE TO FUEL EXHAUSTION.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: MANEUVERING

Findings

1. (C) FLUID, FUEL - EXHAUSTION

2. (C) JUDGMENT - POOR - PILOT IN COMMAND

3. (C) REFUELING - NOT PERFORMED - PILOT IN COMMAND

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings
4. TERRAIN CONDITION - GROUND

Page 2 of 5 FTW85LA082

Factual Information

Pilot Information

Certificate:	Commercial	Age:	53,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 23, 1983
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	531 hours (Total, all aircraft), 55 hours (Total, this make and model), 389 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	FAIRCHILD	Registration:	N48252
Model/Series:	M-62A M-62A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	T43-7213
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	August 1, 1984 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1069 Hrs	Engine Manufacturer:	RANGER
ELT:	Installed	Engine Model/Series:	6-440-C2
Registered Owner:	JOHN L. STEELE	Rated Power:	175 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 FTW85LA082

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	SAT ,809 ft msl	Distance from Accident Site:	25 Nautical Miles
Observation Time:	17:30 Local	Direction from Accident Site:	20°
Lowest Cloud Condition:	Scattered / 12000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 25000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	22°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	SAN ANTONIO , TX (74R)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	17:10 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Grass/turf
Airport Elevation:		Runway Surface Condition:	Dry
Runway Used:	6	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	29.27901,-98.479301(est)

Page 4 of 5 FTW85LA082

Administrative Information

Investigator In Charge (IIC): Mcfall, T

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=21648

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 FTW85LA082