

Aviation Investigation Final Report

Location:	TULSA, Oklahoma		Accident Number:	FTW86LA017
Date & Time:	October 19, 1985, 16	:33 Local	Registration:	N2952N
Aircraft:	CESSNA	310	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 Minor
Flight Conducted Under:	Part 91: General avia	tion - Personal		

Analysis

THE PLT EXPERIENCED FUEL EXHAUSTION WHILE ON FINAL APCH FOR LANDING ON RWY 35L AT TULSA INTERNATIONAL ARPT, OK. THE ACFT UNDERSHOT THE RWY BY 1/2 TO 3/4 OF A MILE WHERE IT CONTACTED RAILROAD TRACKS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings 1. FLUID,FUEL - EXHAUSTION 2. (C) PREFLIGHT PLANNING/PREPARATION - IMPROPER - PILOT IN COMMAND 3. (C) FUEL SUPPLY - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING Phase of Operation: DESCENT - EMERGENCY Occurrence #3: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:		Age:	Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N2952N
Model/Series:	310 310	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	31035039
Landing Gear Type:	Retractable - Tricycle	Seats:	5
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	4600 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	0-470-B
Registered Owner:		Rated Power:	240 Horsepower
Operator:	ADA AIRCRAFT MUSEUM INC.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	TUL ,676 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	16:40 Local	Direction from Accident Site:	350°
Lowest Cloud Condition:	Unknown / 4500 ft AGL	Visibility	6 miles
Lowest Ceiling:	Overcast / 4500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	260°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	21°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	NORMAN , OK	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	VFR
Departure Time:	00:00 Local	Type of Airspace:	

Airport Information

Airport:	TULSA INTERNATIONAL TUL	Runway Surface Type:	Asphalt
Airport Elevation:	676 ft msl	Runway Surface Condition:	Dry
Runway Used:	35L	IFR Approach:	None
Runway Length/Width:	5498 ft / 150 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	36.190315,-95.910697(est)

Administrative Information

Investigator In Charge (IIC):	Johnson, J	
Additional Participating Persons:	MANUEL LOPEZ; OKLAHOMA , OK	
Original Publish Date:		
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=21987	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.