

Aviation Investigation Final Report

Location:	HOLDEN, Louisiana		Accident Number:	FTW87LA020
Date & Time:	November 19, 1986,	08:40 Local	Registration:	N1245F
Aircraft:	BARNES	FIREFLY 7	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Instructional			

Analysis

A COMMERCIALLY RATED PILOT ON AN INSTRUCTIONAL FLIGHT WAS ATTEMPTING A TOUCH AND GO LANDING IN THE MEDIAN OF HIWAY I-12 1 MILE EAST OF HOLDEN, LA. THE PILOT FAILED TO SEE AND AVOID SOME POWER LINES SUBSTANTIALLY DAMAGING THE BALLOON. THE PILOT AND STUDENT PILOT WERE NOT INJURED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: LANDING

Findings

1. (F) OBJECT - WIRE, TRANSMISSION

2. (C) VISUAL LOOKOUT - POOR - PILOT IN COMMAND

3. (F) JUDGMENT - POOR - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: DESCENT - UNCONTROLLED

Factual Information

Pilot Information

Certificate:	Commercial	Age:	39,Male
Airplane Rating(s):	None	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Balloon	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None None	Last FAA Medical Exam:	
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	625 hours (Total, all aircraft), 625 hours (Total, this make and model), 612 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BARNES	Registration:	N1245F
Model/Series:	FIREFLY 7 FIREFLY 7	Aircraft Category:	Balloon
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	160
Landing Gear Type:		Seats:	
Date/Type of Last Inspection:	August 9, 1986 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	Unknown
Airframe Total Time:	105 Hrs	Engine Manufacturer:	NONE
ELT:	Not installed	Engine Model/Series:	NONE
Registered Owner:	PHIL MACNUTT	Rated Power:	
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Thin Overcast / 2500 ft AGL	Visibility	5 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	08:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Grass/turf
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	30.579885,-90.669715(est)

Administrative Information

Investigator In Charge (IIC):	Edwards, Admond	
Additional Participating Persons:	RALPH L WILSON; FORT WORTH , TX FLOYD DOCKUM; BATON ROUGE , LA	
Original Publish Date:	March 10, 1988	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=22301	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.