



Aviation Investigation Final Report

Location: DE QUINCY, Louisiana Accident Number: FTW87LA101

Date & Time: April 23, 1987, 14:00 Local Registration: N414A

Aircraft: SIKORSKY S-55B Aircraft Damage: Substantial

Defining Event: 1 Serious

Flight Conducted Under: Part 137: Agricultural

Analysis

THE PILOT EXPERIENCED AN ENGINE SURGE FOLLOWED BY A COMPLETE LOSS OF POWER DURING A SWATH RUN OF A TREE SPRAYING AG OPERATION. THE HELICOPTER WAS OVER A DENSELY WOODED AREA AND AUTOROTATED INTO TREES. THE OWNER WAS AWARE OF A CARBURETOR PROBLEM AND HAD ALREADY OBTAINED A REBUILT CARBURETOR FOR THE ENGINE, HOWEVER, IT HAD NOT YET BEEN INSTALLED WHEN THE ACCIDENT OCCURRED. A POST ACCIDENT EXAMINATION OF THE ENGINE WAS NOT CONDUCTED. THEREFORE, THE EXACT CAUSE OF THE ENGINE FAILURE IS UNDETERMINED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER

Phase of Operation: MANEUVERING - AERIAL APPLICATION

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

2. (F) OPERATION WITH KNOWN DEFICIENCIES IN EQUIPMENT - INTENTIONAL - COMPANY/OPERATOR MANAGEMENT

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: DESCENT - EMERGENCY

Findings

3. (F) OBJECT - TREE(S)

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Findings

4. (F) TERRAIN CONDITION - NONE SUITABLE

Page 2 of 6 FTW87LA101

Factual Information

Pilot Information

Certificate:	Commercial	Age:	39,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land; Multi- engine sea	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	8000 hours (Total, all aircraft), 6000 hours (Total, this make and model), 5 hours (Last 24 hours, all aircraft)		

Page 3 of 6 FTW87LA101

Aircraft and Owner/Operator Information

Aircraft Make:	SIKORSKY	Registration:	N414A
Model/Series:	S-55B S-55B	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	55279
Landing Gear Type:	Tricycle	Seats:	1
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	7200 lbs
Time Since Last Inspection:	70 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	WRIGHT
ELT:	Not installed	Engine Model/Series:	R-1300
Registered Owner:	GULF SOUTH	Rated Power:	600 Horsepower
Operator:	DENNIS W. ROGERS	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	7 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	2 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	29°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	DEQUINEY , LA (5R8)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Page 4 of 6 FTW87LA101

Airport Information

Airport:		Runway Surface Type:	Dirt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Vegetation
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	

Page 5 of 6 FTW87LA101

Administrative Information

Investigator In Charge (IIC):	Johnson, J	
Additional Participating Persons:	EARL MCCARTHY; BATON ROUGE , LA	
Original Publish Date:	October 6, 1988	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=22352	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 FTW87LA101