

Aviation Investigation Final Report

Location:	PATTERSON, Louisia	ana	Accident Number:	FTW88DRD15
Date & Time:	July 12, 1988, 13:00	Local	Registration:	N4825Q
Aircraft:	CESSNA	A188B	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 137: Agricultura	I		

Analysis

SHORTLY AFTER TAKEOFF, THE ENGINE LOST POWER & THE PLT DUMPED HIS LOAD. SUBSEQUENTLY, THE ACFT CRASH LANDED IN A CANE FIELD. NO PREIMPACT MECHANICAL PROBLEMS COULD BE FOUND WITH THE ENGINE OR FUEL SYSTEM. WATER WAS FOUND IN THE FUEL TANK OUTLET SCREEN, ALTHOUGH NONE WAS FOUND IN THE ENGINE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings 1. (C) FLUID,FUEL - WATER 2. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING Phase of Operation: DESCENT - EMERGENCY

Findings 3. LOAD JETTISON - PERFORMED -----

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: LANDING

Findings

4. (F) TERRAIN CONDITION - CROP 5. (F) TERRAIN CONDITION - ROUGH/UNEVEN

6. (F) TERRAIN CONDITION - SOFT

Factual Information

Pilot Information

Certificate:	Commercial	Age:	37,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	May 27, 1988
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	1741 hours (Total, all aircraft), 1394 hours (Total, this make and model), 7 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N4825Q
Model/Series:	A188B A188B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	18802562T
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	March 26, 1988 Annual	Certified Max Gross Wt.:	4200 lbs
Time Since Last Inspection:	7 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2601 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Not installed	Engine Model/Series:	IO-520-D23
Registered Owner:	BLANCO AG AVIATION INC	Rated Power:	300 Horsepower
Operator:	DAVID M. BLANCO	Operating Certificate(s) Held:	
Operator Does Business As:	BLANCO AG AVIATION	Operator Designator Code:	SIQG

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	225°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	35°C / 22°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(PTN)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	HARRY P WILLIAMS MEMORIAL PTN	Runway Surface Type:	Asphalt
Airport Elevation:	9 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	5400 ft / 150 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	29.689067,-91.300971(est)

Administrative Information

Investigator In Charge (IIC):	Bruce, Willard
Additional Participating Persons:	
Original Publish Date:	November 28, 1989
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=22499

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.