

Aviation Investigation Final Report

Location:	SANTA FE, Texas		Accident Number:	FTW89DRA02
Date & Time:	January 22, 1989, 1	15:30 Local	Registration:	N9961
Aircraft:	PITTS	S1A	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 Serious
Flight Conducted Under:	Part 91: General av	viation - Personal		

Analysis

ACFT SETTLED ON FINAL APP, STRUCK PWR LINES, AND SUBSEQUENTLY CRASHED ON THE AIRPORT. PLT WAS FAMILIAR WITH THE AIRPORT AND THE LINES WERE MARKED WITH HIGH VIS BALLS. PLT COULD NOT REMEMBER ANYTHING ABOUT THE ACCIDENT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: PILOT IN COMMAND FAILED TO MAINTAIN ADEQUATE ALTITUDE AND CLEARANCE ON FINAL APPROACH.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings 1. OBJECT - WIRE, TRANSMISSION (MARKED) 2. (C) CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: DESCENT - UNCONTROLLED

Factual Information

Pilot Information

Certificate:	Private	Age:	54.Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 29, 1987
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1450 hours (Total, all aircraft), 394 hours (Total, this make and model), 1400 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PITTS	Registration:	N9961
Model/Series:	S1A S1A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	1969 WA
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	May 4, 1988 Annual	Certified Max Gross Wt.:	1100 lbs
Time Since Last Inspection:	18 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	604 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	0-320
Registered Owner:	JOHNSON, LAWRENCE F.	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
conditions at Accident Site.		Condition of Light.	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	5 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:30 Local	Type of Airspace:	Class G

Airport Information

Airport:	REBEL FIELD TX66	Runway Surface Type:	Grass/turf
Airport Elevation:	25 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	1600 ft / 100 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	29.37994,-95.08934(est)

Administrative Information

Investigator In Charge (IIC):	Knuckey, Michael
Additional Participating Persons:	
Original Publish Date:	January 31, 1991
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=22715

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.