



Aviation Investigation Final Report

Location: SAN ANTONIO, Texas Accident Number: FTW90LA011

Date & Time: October 15, 1989, 17:55 Local Registration: N3893V

Aircraft: CESSNA 195 Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT STATED THAT, AFTER A BOUNCED LANDING, SHE ATTEMPTED TO RECOVER BY PULLING THE FLIGHT CONTROL FULL AFT. THE AIRCRAFT STALLED AND COLLIDED WITH THE TERRAIN.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: PILOT'S IMPROPER RECOVERY FROM A BOUNCED LANDING AND SUBSEQUENT STALL OF THE AIRCRAFT.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND

2. (C) STALL/MUSH - ENCOUNTERED - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Factual Information

Pilot Information

Certificate:	Commercial	Age:	38,Female
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	December 2, 1987
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	810 hours (Total, all aircraft), 242 hours (Total, this make and model), 705 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 2 of 5 FTW90LA011

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N3893V
Model/Series:	195 195	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	7365
Landing Gear Type:	Tailwheel	Seats:	5
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	JACOBS
ELT:		Engine Model/Series:	R-755-A2
Registered Owner:	MARY L. & MAUREEN L. MCMASTER	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

- Intercent of the first term			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	32°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	BOERNE STAGEFLD, TX (5C1)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	17:10 Local	Type of Airspace:	Class D

Page 3 of 5 FTW90LA011

Airport Information

Airport:	BOERNE STAGE 5C1	Runway Surface Type:	Asphalt
Airport Elevation:	1380 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	3400 ft / 40 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	

Page 4 of 5 FTW90LA011

Administrative Information

Investigator In Charge (IIC): Griffin, John

Additional Participating Persons:

Original Publish Date: June 25, 1992

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=23064

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 FTW90LA011