



Aviation Investigation Final Report

Location: ANTIOCH, California Accident Number: LAX83LA409

Date & Time: August 25, 1983, 13:45 Local Registration: N76112

Aircraft: CESSNA 140 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation

Analysis

THE PLT STATED THAT AFTER THE ACFT BOUNCED HE TRIED 'TO SALVAGE A BAD LANDING.' THE ACFT CAME TO REST INVERTED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: NOSE OVER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) LEVEL OFF - IMPROPER - PILOT IN COMMAND

2. (C) RECOVERY FROM BOUNCED LANDING - INADEQUATE - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	61,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	November 16, 1982
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	3600 hours (Total, all aircraft), 55 hours (Total, this make and model), 30 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 2 of 5 LAX83LA409

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N76112
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	10509
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	June 7, 1983 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	10 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2611 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	C-85
Registered Owner:	GEE BERO AERO	Rated Power:	85 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:			Direction from Accident Site:	
Lowest Cloud Condition:	Clear		Visibility	20 miles
Lowest Ceiling:	None		Visibility (RVR):	
Wind Speed/Gusts:	8 knots /		Turbulence Type Forecast/Actual:	/
Wind Direction:	250°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:			Temperature/Dew Point:	-17°C / -12°C
Precipitation and Obscuration:	No Obscurat	ion; No Precipita	ition	
Departure Point:	SAN JOSE	, CA (RHV)	Type of Flight Plan Filed:	None
Destination:			Type of Clearance:	None
Departure Time:	00:00 Local		Type of Airspace:	Class G

Page 3 of 5 LAX83LA409

Airport Information

Airport:	ANTIOCH 012	Runway Surface Type:	Asphalt
Airport Elevation:	180 ft msl	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	2500 ft / 27 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.989696,-121.810836(est)

Page 4 of 5 LAX83LA409

Administrative Information

Investigator In Charge (IIC):	Llorente, A.
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=23834

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX83LA409