



Aviation Investigation Final Report

Location: HEALDSBURG, California Accident Number: LAX84LA154

Date & Time: January 24, 1984, 14:00 Local Registration: N5026S

Aircraft: BELLANCA 7ECA Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

THE PLT REPORTED THAT A GUST OF WIND PUSHED UP THE LEFT WING & THE ACFT VEERED OFF THE RWY. THE ACFT THEN WENT DOWN A SHALLOW GRADE & IMPACTED BUSHES. HE REPORTED THE WIND WAS FROM 330 DEG AT 10 GUSTING 18 KTS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - GUSTS

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Student	Age:	39,Male
Airplane Rating(s):	None	Seat Occupied:	Front
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 3, 1983
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	57 hours (Total, all aircraft), 57 hours (Total, this make and model), 26 hours (Pilot In Command, all aircraft), 46 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELLANCA	Registration:	N5026S
Model/Series:	7ECA 7ECA	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	1326-79
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	October 13, 1983 Annual	Certified Max Gross Wt.:	1350 lbs
Time Since Last Inspection:	58 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1958 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-235-K2C
Registered Owner:	CHUCK HUNTER	Rated Power:	115 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:	AERO SPORT	Operator Designator Code:	

Page 2 of 4 LAX84LA154

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots / 18 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	330°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	19°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	SONOMA , CA (0Q3)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:30 Local	Type of Airspace:	Class G

Airport Information

Airport:	HEALDSBURG MUNI 031	Runway Surface Type:	Asphalt
Airport Elevation:	300 ft msl	Runway Surface Condition:	Dry
Runway Used:	31	IFR Approach:	None
Runway Length/Width:	2707 ft / 45 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	38.629627,-122.889411(est)

Page 3 of 4 LAX84LA154

Administrative Information

Investigator In Charge (IIC):	Pollack, Wayne	
Additional Participating Persons:	PAUL FLOOD; OAKLAND , CA	
Original Publish Date:		
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=24150	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 LAX84LA154