



Aviation Investigation Final Report

Location: AFTON, California Accident Number: LAX86FVG02

Date & Time: March 21, 1986, 13:00 Local Registration: N8327

Aircraft: SIKORSKY S-55 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

THE ACFT WAS LANDED OFF THE ARPT IN A FORCED LANDING AFTER A PWR LOSS. THE ACFT WAS DAMAGED IN THE HARD LANDING. ENG TEARDOWN SHOWED THE R/H MAGNETO MODEL S7LV-2 HAD STRIPPED DISTRIBUTOR DRIVE GEARS. NO OTHER ABNORMALITIES NOTED. THE TSO OF THE MAG WAS CALCULATED TO BE 669.2 HRS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF

Phase of Operation: MANEUVERING - AERIAL APPLICATION

Findings

1. (C) IGNITION SYSTEM, MAGNETO - FAILURE, TOTAL

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: HARD LANDING Phase of Operation: LANDING - FLARE/TOUCHDOWN

Page 2 of 5 LAX86FVG02

Factual Information

Pilot Information

Certificate:	Commercial	Age:	52,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	April 1, 1985
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	5000 hours (Total, all aircraft), 4500 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	SIKORSKY	Registration:	N8327
Model/Series:	S-55 S-55	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Limited (Special)	Serial Number:	55-231
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	December 2, 1985 Annual	Certified Max Gross Wt.:	7200 lbs
Time Since Last Inspection:	190 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	8600 Hrs	Engine Manufacturer:	Curtis Wright
ELT:	Not installed	Engine Model/Series:	R-1300-3D
Registered Owner:		Rated Power:	700 Horsepower
Operator:	AVAG CORP.	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 LAX86FVG02

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Dirt
Airport Elevation:		Runway Surface Condition:	Wet
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.449932,-121.389106(est)

Page 4 of 5 LAX86FVG02

Administrative Information

Investigator In Charge (IIC):	Engelsman, Donald
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=24976

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX86FVG02