



Aviation Investigation Final Report

Location:	PACOIMA, California	Accident Number:	LAX86LA256
Date & Time:	June 17, 1986, 13:40 Local	Registration:	N89403
Aircraft:	CESSNA 140	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

THE PLT LOST CONTROL OF THE ACFT DURING LANDING. A WITNESS STATED THAT WHEN THE ACFT WAS ABOUT ONE-FOURTH OF THE WAY DOWN THE RWY, IT BEGAN PORPOISING AND THEN FLIPPED OVER ON ITS BACK.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT
Phase of Operation: LANDING

Findings

1. (C) AIRCRAFT HANDLING - IMPROPER - PILOT IN COMMAND
2. (F) LACK OF TOTAL EXPERIENCE IN KIND OF AIRCRAFT - PILOT IN COMMAND

Occurrence #2: NOSE OVER
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Factual Information

Pilot Information

Certificate:	Private	Age:	42, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	April 2, 1985
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	207 hours (Total, all aircraft), 21 hours (Total, this make and model), 122 hours (Pilot In Command, all aircraft), 21 hours (Last 90 days, all aircraft), 21 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N89403
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	8435
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	March 13, 1986 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1600 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	E-85
Registered Owner:	JOSEPH E.BOLYARD	Rated Power:	85 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	29°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	SANTA PAULA , CA (SZP)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	WHITEMAN WHP	Runway Surface Type:	Asphalt
Airport Elevation:	1004 ft msl	Runway Surface Condition:	Dry
Runway Used:	12	IFR Approach:	None
Runway Length/Width:	3725 ft / 40 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.250083,-118.410293(est)

Administrative Information

Investigator In Charge (IIC): Schutte, Audrey

Additional Participating Persons: DAVE ELLIOTT; VAN NUYS , CA

Original Publish Date:

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=25185>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).