



Aviation Investigation Final Report

LANCASTER, California Accident Number: LAX89LA148

Date & Time: April 1, 1989, 12:39 Local Registration: N3508Z

Aircraft: PIPER PA-22 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

AFTER LANDING ON RWY 24, THE PLT ELECTED TO EXIT AT THE MIDFIELD INTERSECTION. AS HE WAS TAXIING OFF THE RWY, A STRONG GUST OF WIND OCCURRED WHICH BLEW THE ACFT OVER ON ITS TOP.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: IMPROPER PLANNING/DECISION BY THE PILOT. STRONG/GUSTY WINDS CONTRIBUTED TO THE ACCIDENT.

Findings

Occurrence #1: NOSE OVER

Phase of Operation: TAXI - FROM LANDING

Findings

1. (C) PLANNING/DECISION - IMPROPER - PILOT IN COMMAND

2. (F) WEATHER CONDITION - HIGH WIND

3. (F) WEATHER CONDITION - GUSTS

Factual Information

Pilot Information

Certificate:	Private	Age:	46,U
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	May 27, 1987
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	300 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N3508Z
Model/Series:	PA-22 PA-22	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-320
Registered Owner:	KOFLER, CARL	Rated Power:	160 Horsepower
Operator:	UNKNOWN	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 LAX89LA148

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 2000 ft AGL	Visibility	40 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	25 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	290°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	COTTONWOOD , AZ	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:25 Local	Type of Airspace:	

Airport Information

Airport:	WILLIAM J FOX AIRFIELD WJF	Runway Surface Type:	Asphalt
Airport Elevation:	2347 ft msl	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	5001 ft / 150 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 3 of 4 LAX89LA148

Administrative Information

Investigator In Charge (IIC): Isbell, Shelby

Additional Participating Persons:

Original Publish Date: April 19, 1990

Last Revision Date:
Investigation Class: Class
Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=26369

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 LAX89LA148