



Aviation Investigation Final Report

Location: WICKENBURG, Arizona Accident Number: LAX90LA342

Date & Time: September 26, 1990, 13:35 Local Registration: N49595

Aircraft: PIPER J-3C-115 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

WHILE LANDING ON RUNWAY 23 AT WICKENBURG MUNI AIRPORT, WICKENBURG, ARIZONA, THE PILOT FAILED TO MAINTAIN DIRECTIONAL CONTROL AND GROUND LOOPED. THE AIRPLANE EXITED THE RUNWAY AND COLLIDED WITH THE TERRAIN. THE PILOT DID NOT REPORT ANY MECHANICAL DIFFICULTIES AND GROUND WITNESSES REPORTED THAT THE SURFACE WINDS WERE LIGHT AND VARIABLE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN DIRECTIONAL CONTROL.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	53.Male
Certificate.	riivate	Age.	55,iviale
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	June 1, 1989
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N49595
Model/Series:	J-3C-115 J-3C-115	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	G-113
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1220 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	0-65
Registered Owner:		Rated Power:	65 Horsepower
Operator:	GENESIS AVIATION	Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 LAX90LA342

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VM	C)	Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:			Direction from Accident Site:	
Lowest Cloud Condition:	Clear		Visibility	50 miles
Lowest Ceiling:	None		Visibility (RVR):	
Wind Speed/Gusts:	/		Turbulence Type Forecast/Actual:	/
Wind Direction:	0°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:			Temperature/Dew Point:	27°C / -18°C
Precipitation and Obscuration:	No Obscura	ation; No Precipita	ation	
Departure Point:	TUCSON	, AZ (RYN)	Type of Flight Plan Filed:	None
Destination:			Type of Clearance:	None
Departure Time:	10:00 Loca	I	Type of Airspace:	

Airport Information

Airport:	WICKENBURG E25	Runway Surface Type:	Asphalt
Airport Elevation:	2423 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	5050 ft / 60 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 3 of 4 LAX90LA342

Administrative Information

Investigator In Charge (IIC): Wilcox, T.

Additional Participating
Persons:

Original Publish Date: December 30, 1992

Last Revision Date:
Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=26937

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 LAX90LA342