



Aviation Investigation Final Report

Location: SOLDOTNA, Alaska Accident Number: ANC97LA070

Date & Time: March 30, 1997, 14:15 Local Registration: N920NB

Aircraft: Piper J-3 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that his airplane hit the runway hard while landing in gusty wind conditions. The airplane bounced, landed hard again, and collapsed the right main landing gear. The right wing struck the ground, damaging the main spar.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate compensation for the gusty wind conditions, and his improper recovery from a bounced landing. A factor associated with the accident was the gusty wind.

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) WEATHER CONDITION - GUSTS

2. (C) COMPENSATION FOR WIND CONDITIONS - INADEQUATE - PILOT IN COMMAND

3. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings 4. LANDING GEAR, MAIN GEAR - OVERLOAD

Page 2 of 6 ANC97LA070

Factual Information

On March 30, 1997, about 1415 Alaska standard time, a wheel equipped Piper J-3 airplane, N920NB, sustained substantial damage while landing at the Soldotna Airport, Soldotna, Alaska. The solo private pilot was not injured. The local, 14 CFR Part 91 flight operated in visual meteorological conditions without a flight plan.

A Federal Aviation Administration (FAA) inspector inspected the airplane and interviewed the pilot on May 12. According to the FAA inspector, the pilot was landing in gusty wind conditions. The airplane landed hard, bounced, and upon the second contact with the runway, the right main landing gear collapsed. The right wing subsequently struck the runway, and damaged the main spar.

The pilot did not complete the NTSB Accident Report Form that was mailed to him.

Pilot Information

Certificate:	Private	Age:	58,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	February 20, 1997
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	240 hours (Total, all aircraft)		

Page 3 of 6 ANC97LA070

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N920NB
Model/Series:	J-3 J-3	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1220 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:		Engine Model/Series:	A65-8
Registered Owner:	ROBERT J. CONDON	Rated Power:	65 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	(SQX)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Page 4 of 6 ANC97LA070

Airport Information

Airport:	SOLDOTNA SXQ	Runway Surface Type:	Asphalt
Airport Elevation:	107 ft msl	Runway Surface Condition:	
Runway Used:	25	IFR Approach:	None
Runway Length/Width:	4973 ft / 130 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	60.320915,-150.789566(est)

Page 5 of 6 ANC97LA070

Administrative Information

Investigator In Charge (IIC):	Labelle, James	
Additional Participating Persons:	GENE CORDLE; ANCHORAGE , AK	
Original Publish Date:	May 4, 1998	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=3003	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC97LA070