

# **Aviation Investigation Final Report**

Location:	GENESEO, New Yo	rk	Accident Number:	NYC86LA235
Date & Time:	September 14, 198	86, 10:40 Local	<b>Registration:</b>	N7215P
Aircraft:	PIPER	PA-24-250	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 Minor, 1 None
Flight Conducted Under:	Part 91: General av	viation - Personal		

### **Analysis**

THE AIRCRAFT LOST POWER ON APPROACH TO GENESEO AIRPORT. INVESTIGATION DID NOT REVEAL ANY PREIMPACT MALFUNCTION/FAILURE. CONDITIONS CONDUCIVE TO CARBURETOR ICING EXISTED AT THE TIME OF THE ACCIDENT.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: APPROACH

Findings 1. (C) REASON FOR OCCURRENCE UNDETERMINED 2. WEATHER CONDITION - CARBURETOR ICING CONDITIONS

Occurrence #2: FORCED LANDING Phase of Operation: DESCENT - EMERGENCY

# **Factual Information**

#### **Pilot Information**

Certificate:	Private	Age:	36,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	July 17, 1986
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	200 hours (Total, all aircraft), 200 hours (Total, this make and model), 30 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

### Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N7215P
Model/Series:	PA-24-250 PA-24-250	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	24-2385
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	2900 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3790 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-540-A1A5
Registered Owner:	EWS CORP.	Rated Power:	250 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 4000 ft AGL	Visibility	15 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	11°C / 7°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	ELLENVILLE , NY (N89 )	Type of Flight Plan Filed:	None
Destination:	GENESEO , NY (D52 )	Type of Clearance:	None
Departure Time:	08:15 Local	Type of Airspace:	Class G

# **Airport Information**

Airport:	GENESEO D52	Runway Surface Type:	Grass/turf
Airport Elevation:	560 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	26	IFR Approach:	None
Runway Length/Width:	3100 ft / 90 ft	VFR Approach/Landing:	Forced landing;Traffic pattern

# Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	42.790611,-77.809967(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Marcantelli, Vincent
Additional Participating Persons:	
Original Publish Date:	March 10, 1988
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=30420

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.