



# **Aviation Investigation Final Report**

**Location**: NO KINGSTOWN, Rhode Island **Accident Number**: NYC87LA270

Date & Time: July 30, 1987, 14:35 Local Registration: N1223J

Aircraft: ROCKWELL 112A Aircraft Damage: Substantial

**Defining Event:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

THE AIRCRAFT BOUNCED ON LANDING AND DIRECTIONAL CONTROL WAS LOST. THE AIRPLANE VEERED TO THE LEFT SIDE OF THE RUNWAY AND STRUCK A PILE OF RUBBLE AND CONTINUED INTO THE BAY.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### **Findings**

1. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

------

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

-----

Occurrence #3: NOSE OVER Phase of Operation: LANDING - ROLL

Page 2 of 5 NYC87LA270

## **Factual Information**

#### **Pilot Information**

Certificate:	Private	Age:	44,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	December 8, 1986
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	779 hours (Total, all aircraft), 230 hours (Total, this make and model), 250 hours (Pilot In Command, all aircraft), 23 hours (Last 90 days, all aircraft)		

## **Aircraft and Owner/Operator Information**

Aircraft Make:	ROCKWELL	Registration:	N1223J
Model/Series:	112A 112A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	223
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	October 1, 1986 Annual	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1205 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	O-320-A2B
Registered Owner:	DONALD J. DINOFRIO	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 NYC87LA270

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	22°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	QUONSET STATE OQU	Runway Surface Type:	Asphalt;Concrete
Airport Elevation:	20 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	8000 ft / 150 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 4 of 5 NYC87LA270

#### **Administrative Information**

Investigator In Charge (IIC):	Ghiorsi, Frank
Additional Participating Persons:	
Original Publish Date:	May 26, 1989
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=30744

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 NYC87LA270