



Aviation Investigation Final Report

Location: FT. PIERCE, Florida Accident Number: MIA84LA194

Date & Time: June 27, 1984, 13:30 Local Registration: N5496F

Aircraft: MOONEY A-2A Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE ENG LOST POWER ABOUT 30 SECS AFTER THE PLT TOOK OFF. DURING A FORCED LANDING, THE ACFT TOUCHED DOWN SHORT OF THE RWY & THE NOSE GEAR COLLAPSED IN TALL GRASS. NO PREIMPACT MECHANICAL DISCREPANCIES WERE FOUND DURING AN EXAM OF THE ENG.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER

Phase of Operation: CLIMB

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: NOSE GEAR COLLAPSED

Phase of Operation: LANDING

- Findings
 2. (F) TERRAIN CONDITION HIGH VEGETATION
 3. LANDING GEAR, NOSE GEAR OVERLOAD

Page 2 of 5 MIA84LA194

Factual Information

Pilot Information

Certificate:	Private	Age:	50,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 23, 1983
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1732 hours (Total, all aircraft), 1531 hours (Total, this make and model), 1625 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	MOONEY	Registration:	N5496F
Model/Series:	A-2A A-2A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	296
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	December 2, 1983 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1445 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	C-90-16F
Registered Owner:	JOHN P. COUGHLIN	Rated Power:	90 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MIA84LA194

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	VRB ,24 ft msl	Distance from Accident Site:	3 Nautical Miles
Observation Time:	12:50 Local	Direction from Accident Site:	165°
Lowest Cloud Condition:	Scattered / 1500 ft AGL	Visibility	3 miles
Lowest Ceiling:	Broken / 3000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	100°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	29°C / 24°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	FT. PIERCE , FL (FPR)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:30 Local	Type of Airspace:	

Airport Information

Airport:	ST. LUCIE COUNTY FPR	Runway Surface Type:	Asphalt
Airport Elevation:	24 ft msl	Runway Surface Condition:	Dry
Runway Used:	14	IFR Approach:	None
Runway Length/Width:	5000 ft / 200 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	

Page 4 of 5 MIA84LA194

Administrative Information

Investigator In Charge (IIC):	Baro, Edward
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=31152

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MIA84LA194