

Aviation Investigation Final Report

Location:	MIAMI, Florida		Incident Number:	MIA85IA032
Date & Time:	November 13, 1984	, 18:39 Local	Registration:	N1053U
Aircraft:	PIPER	PA-34-200	Aircraft Damage:	Minor
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General avi	ation - Personal		

Analysis

THE NOSE CEAR COLLAPSED DURING A LANDING. AN EXAM DISCLOSED THAT THE HYDRAULIC ACTUATOR FIREWALL MOUNTING BRACKET HAD FAILED PRIOR TO COMPLETE EXTENSION OF THE NOSE GEAR. PIPER SERVICE BULLETIN, SB 413, RELATED TO THIS PROBLEM; HOWEVER, NO LOGBOOK ENTRY WAS FOUND TO VERIFY COMPLIANCE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this incident to be:

Findings

Occurrence #1: NOSE GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

1. (C) LANDING GEAR, NORMAL RETRACTION/EXTENSION ASSEMBLY - FAILURE, TOTAL

Factual Information

Pilot Information

Certificate:	Commercial	Age:	61,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	July 2, 1984
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	5688 hours (Total, all aircraft), 130 hours (Total, this make and model), 15 hours (Last 90 days, all aircraft), 14 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N1053U
Model/Series:	PA-34-200 PA-34-200	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	34-750036
Landing Gear Type:	Retractable - Tricycle	Seats:	7
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	1125 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	10-360
Registered Owner:	GPC AVIATION, INC.	Rated Power:	200 Horsepower
Operator:	ROBERT VERDAGUER	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night/dark
Observation Facility, Elevation:	TMB ,10 ft msl	Distance from Accident Site:	
Observation Time:	18:00 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	16°C / 10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	LABELLE , FL (LBU)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	17:30 Local	Type of Airspace:	Class E

Airport Information

Airport:	ΤΑΜΙΑΜΙ ΤΜΒ	Runway Surface Type:	Asphalt
Airport Elevation:	10 ft msl	Runway Surface Condition:	Dry
Runway Used:	9	IFR Approach:	None
Runway Length/Width:	5000 ft / 150 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Minor
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	25.650362,-80.409973(est)

Administrative Information

Investigator In Charge (IIC):	Hill, Bruce
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=31276

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.