



# **Aviation Investigation Final Report**

Location: NEW SMYRNA BCH, Florida Accident Number: MIA86LA090

Date & Time: March 4, 1986, 12:30 Local Registration: N53805

Aircraft: BELLANCA 7KCAB Aircraft Damage: Substantial

**Defining Event:** 1 Minor

Flight Conducted Under: Part 91: General aviation

### **Analysis**

THE PLT STATED THAT JUST AFTER PICKING UP A BANNER, THE ACFT STALLED AND STARTED TO ROLL TO THE LEFT. THE PLT WAS UNABLE TO RECOVER BEFORE THE ACFT IMPACTED THE GROUND.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: TAKEOFF - INITIAL CLIMB

#### **Findings**

1. (C) PULL-UP - EXCESSIVE - PILOT IN COMMAND

2. (C) STALL - INADVERTENT - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial	Age:	45,Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Expired	Last FAA Medical Exam:	November 14, 1983
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1613 hours (Total, all aircraft), 42 hours (Total, this make and model), 1400 hours (Pilot In Command, all aircraft), 8 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	BELLANCA	Registration:	N53805
Model/Series:	7KCAB 7KCAB	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Aerobatic; Normal	Serial Number:	545-75
Landing Gear Type:	Tailwheel	Seats:	3
Date/Type of Last Inspection:	March 1, 1985 Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1600 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-320-E2A
Registered Owner:	ROBERT E. LOWERY, III	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 MIA86LA090

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DAB ,35 ft msl	Distance from Accident Site:	12 Nautical Miles
Observation Time:	12:52 Local	Direction from Accident Site:	330°
<b>Lowest Cloud Condition:</b>	Scattered / 3300 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	13 knots / 21 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	250°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	22°C / 11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	12:20 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	NEW SMYRNA BEACH 34J	Runway Surface Type:	Asphalt
Airport Elevation:	12 ft msl	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	3200 ft / 75 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	

Page 3 of 4 MIA86LA090

#### **Administrative Information**

Investigator In Charge (IIC):	Hill, Bruce
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=31584

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 MIA86LA090