



# **Aviation Investigation Final Report**

| Location:               | SAN JUAN, Puerto Rico                          | Accident Number: | MIA86LA127  |
|-------------------------|--|------------------|-------------|
| Date & Time:            | April 22, 1986, 09:30 Local                    | Registration:    | N6155V      |
| Aircraft:               | Consolidated Aeronautics Inc.<br>LAKE LA-4-200 | Aircraft Damage: | Substantial |
| Defining Event:         |  | Injuries:        | 1 None      |
| Flight Conducted Under: | Part 91: General aviation - Instructional      |                  |             |

#### **Analysis**

THE PLT STATED THAT ON LANDING THE ACFT STARTED TO PORPOISE.HE LOST CONTROL, THE LANDING GEAR COLLAPSED AND THE ACFT SLID TO A STOP ON THE RWY.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND 2. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND

Occurrence #2: GEAR COLLAPSED Phase of Operation: LANDING - ROLL

# **Factual Information**

#### **Pilot Information**

| Certificate:              | Student  | Age:                              | 55,Male           |
|---------------------------|--|-----------------------------------|-------------------|
| Airplane Rating(s):       | None   | Seat Occupied:                    | Left              |
| Other Aircraft Rating(s): | None   | Restraint Used:                   |                   |
| Instrument Rating(s):     | None   | Second Pilot Present:             | No                |
| Instructor Rating(s):     | None   | Toxicology Performed:             | No                |
| Medical Certification:    | Class 3 Valid Medicalw/<br>waivers/lim   | Last FAA Medical Exam:            | November 18, 1985 |
| Occupational Pilot:       | UNK  | Last Flight Review or Equivalent: |                   |
| Flight Time:              | 70 hours (Total, all aircraft), 34 hours (Total, this make and model), 2 hours (Pilot In Command,<br>all aircraft), 32 hours (Last 90 days, all aircraft), 8 hours (Last 24 hours, all aircraft) |                                   |                   |

#### Aircraft and Owner/Operator Information

| Aircraft Make:                   | Consolidated Aeronautics Inc. | Registration:                     | N6155V          |
|----------------------------------|-------------------------------|-----------------------------------|-----------------|
| Model/Series:                    | LAKE LA-4-200 LAKE LA-4-      | Aircraft Category:                | Airplane        |
| Year of Manufacture:             |                               | Amateur Built:                    |                 |
| Airworthiness Certificate:       | Normal                        | Serial Number:                    | 809             |
| Landing Gear Type:               | Retractable - Tricycle        | Seats:                            | 4               |
| Date/Type of Last<br>Inspection: | December 20, 1985 Annual      | Certified Max Gross Wt.:          | 2690 lbs        |
| Time Since Last Inspection:      |                               | Engines:                          | 1 Reciprocating |
| Airframe Total Time:             | 839 Hrs                       | Engine Manufacturer:              | LYCOMING        |
| ELT:                             | Installed, not activated      | Engine Model/Series:              | IO-360-A1B      |
| Registered Owner:                | HECOR CORPORATION             | Rated Power:                      | 200 Horsepower  |
| Operator:                        |                               | Operating Certificate(s)<br>Held: | None            |
| Operator Does Business As:       |                               | Operator Designator Code:         |                 |

#### Meteorological Information and Flight Plan

| Conditions at Accident Site:     | Visual (VMC)                     | Condition of Light:                     | Day              |
|----------------------------------|----------------------------------|---|------------------|
| Observation Facility, Elevation: | SJU ,10 ft msl                   | Distance from Accident Site:            | 5 Nautical Miles |
| Observation Time:                | 09:44 Local                      | Direction from Accident Site:           | 90°              |
| Lowest Cloud Condition:          | Scattered / 3000 ft AGL          | Visibility                              | 15 miles         |
| Lowest Ceiling:                  | None                             | Visibility (RVR):                       |                  |
| Wind Speed/Gusts:                | 9 knots /                        | Turbulence Type<br>Forecast/Actual:     | /                |
| Wind Direction:                  | 80°                              | Turbulence Severity<br>Forecast/Actual: | /                |
| Altimeter Setting:               | 30 inches Hg                     | Temperature/Dew Point:                  | 28°C / 24°C      |
| Precipitation and Obscuration:   | No Obscuration; No Precipitation |   |                  |
| Departure Point:                 |                                  | Type of Flight Plan Filed:              | None             |
| Destination:                     |                                  | Type of Clearance:                      |                  |
| Departure Time:                  | 08:45 Local                      | Type of Airspace:                       |                  |

## **Airport Information**

| Airport:             | ISLA GRADE MJ1G  | Runway Surface Type:             | Asphalt                   |
|----------------------|------------------|----------------------------------|---------------------------|
| Airport Elevation:   | 10 ft msl        | <b>Runway Surface Condition:</b> | Dry                       |
| Runway Used:         | 9                | IFR Approach:                    | None                      |
| Runway Length/Width: | 5300 ft / 100 ft | VFR Approach/Landing:            | Full stop;Traffic pattern |

## Wreckage and Impact Information

| Crew Injuries:         | 1 None | Aircraft Damage:        | Substantial |
|------------------------|--------|-------------------------|-------------|
| Passenger<br>Injuries: |        | Aircraft Fire:          | None        |
| Ground Injuries:       | N/A    | Aircraft Explosion:     | None        |
| Total Injuries:        | 1 None | Latitude,<br>Longitude: |             |

#### **Administrative Information**

| Investigator In Charge (IIC):        | Hill, Bruce                                  |
|--------------------------------------|--|
| Additional Participating<br>Persons: |  |
| Original Publish Date:               |  |
| Last Revision Date:                  |  |
| Investigation Class:                 | <u>Class</u>                                 |
| Note:                                |  |
| Investigation Docket:                | https://data.ntsb.gov/Docket?ProjectID=31606 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.