



Aviation Investigation Final Report

Location: TUNICA, Mississippi Accident Number: MIA87LA053

Date & Time: December 22, 1986, 11:00 Local Registration: N6907F

Aircraft: CESSNA 150F Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT STATED THAT DURING LANDING ROLL HE LOST CONTROL OF THE ACFT AND IT SWERVED OFF THE RIGHT SIDE OF THE RWY. THE ACFT TRAVELED INTO A PLOWED FIELD AND THE NOSE GEAR COLLAPSED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

2. (C) GROUND LOOP/SWERVE - UNCONTROLLED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings

3. TERRAIN CONDITION - GROUND

Page 2 of 5 MIA87LA053

Factual Information

Pilot Information

Certificate:	Student	Age:	20,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	November 12, 1986
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	18 hours (Total, all aircraft), 18 hours (Total, this make and model), 2 hours (Pilot In Command, all aircraft), 2 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N6907F
Model/Series:	150F 150F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	15063507
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	March 11, 1986 Annual	Certified Max Gross Wt.:	1600 lbs
Time Since Last Inspection:	65 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4601 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	0-200
Registered Owner:	JAMES P. DEMING	Rated Power:	100 Horsepower
Operator:	DELTA FLYING SERVICE	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MIA87LA053

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MEM ,332 ft msl	Distance from Accident Site:	30 Nautical Miles
Observation Time:	10:48 Local	Direction from Accident Site:	30°
Lowest Cloud Condition:	Scattered / 10000 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 25000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	12 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	80°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	7°C / -2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	WALLS (MS65)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:10 Local	Type of Airspace:	Class E

Airport Information

Airport:	TUNICA MUNICIPAL M97	Runway Surface Type:	Asphalt
Airport Elevation:	195 ft msl	Runway Surface Condition:	Dry
Runway Used:	18	IFR Approach:	None
Runway Length/Width:	3200 ft / 60 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.680995,-90.379959(est)

Page 4 of 5 MIA87LA053

Administrative Information

Investigator In Charge (IIC):	Hill, Bruce
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=31838

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MIA87LA053