



Aviation Investigation Final Report

Location: PORT ST. LUCIE, Florida Accident Number: MIA93LA005

Date & Time: October 6, 1992, 12:10 Local Registration: N17803

Aircraft: BEECH A36 Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

DURING THE DESCENT FOR LANDING ABOUT 10 MILES FROM THE DESTINATION ARPT, THE ENG QUIT DUE TO FUEL EXHAUSTION. THE ACFT COLLIDED WITH TREE STUMPS DURING THE FORCED LANDING AND CAME TO REST UPRIGHT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: TOTAL LOSS OF ENGINE POWER DUE TO FUEL EXHAUSTION CAUSED BY POOR PREFLIGHT PLANNING PREPARATION BY THE PILOT IN COMMAND.

Findings

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: CRUISE - NORMAL

Findings

1. (C) FLUID, FUEL - EXHAUSTION

2. (C) PREFLIGHT PLANNING/PREPARATION - POOR - PILOT IN COMMAND

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

3. OBJECT - TREE(S)

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Page 2 of 5 MIA93LA005

Factual Information

Pilot Information

Certificate:	Private	Age:	68,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	2100 hours (Total, all aircraft), 2030 hours (Pilot In Command, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N17803
Model/Series:	A36 A36	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	E1031
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	September 14, 1992 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	13 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1688 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	IO-520-BA
Registered Owner:	CHECKMATE LEASING, INC.	Rated Power:	285 Horsepower
Operator:	CHECKMATE LEASING, INC.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MIA93LA005

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	FPR ,24 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	12:10 Local	Direction from Accident Site:	340°
Lowest Cloud Condition:	Scattered / 1500 ft AGL	Visibility	7 miles
Lowest Ceiling:	Broken / 6000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	WEST PALM BEACH, FL (PBI)	Type of Flight Plan Filed:	None
Destination:	FORT PIERCE , FL (FPR)	Type of Clearance:	None
Departure Time:	11:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	27.370727,-80.309913(est)

Page 4 of 5 MIA93LA005

Administrative Information

Investigator In Charge (IIC): Monville, Timothy

Additional Participating Persons:

Original Publish Date: July 29, 1993

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=33188

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MIA93LA005