



Aviation Investigation Final Report

Location: KLEMME, Iowa Accident Number: MKC83LA210

Date & Time: September 2, 1983, 09:30 Local Registration: N9921G

Aircraft: CESSNA 188A Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

THE ACFT INADVERTENTLY DESCENDED INTO THE TOPS OF A CORN CROP WHILE DISPENSING SMOKE IN PREPARATION FOR SPRAYING. THE INDUCED DRAG SLOWED THE ACFT AND IT LANDED HARD. THE PLT STATED HE DIVERTED HIS HIS ATTN TO THE SPRAY NOZZLES.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: MANEUVERING - AERIAL APPLICATION

Findings

1. (F) TERRAIN CONDITION - CROP

2. (C) PROPER ALTITUDE - NOT MAINTAINED - PILOT IN COMMAND

3. (C) DIVERTED ATTENTION - PILOT IN COMMAND

4. (C) CLEARANCE - MISJUDGED - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Commercial	Age:	34,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 1, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	1550 hours (Total, all aircraft), 200 hours (Total, this make and model), 1402 hours (Pilot In Command, all aircraft), 200 hours (Last 90 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N9921G
Model/Series:	188A 188A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	18800721
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	December 8, 1982 Annual	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:	882 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2925 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	IO-520-D
Registered Owner:	HAMPTON FLYING SERVICE,INC	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 MKC83LA210

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots / 10 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	27°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	KLEMME,IA	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.999443,-93.599075(est)

Page 3 of 4 MKC83LA210

Administrative Information

Investigator In Charge (IIC):	Thorpe, C.
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=33482

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 MKC83LA210