



# **Aviation Investigation Final Report**

Location: RUSSELLVILLE, Arkansas Accident Number: MKC84LA066

Date & Time: November 26, 1983, 17:00 Local Registration: N7843D

Aircraft: PIPER PA-22-150 Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

AFTER LANDING, THE PLT TAXIED TO THE TIE-DOWN AREA. WHILE TURNING INTO A TIEDOWN POSTION, THE RIGHT MAIN GEAR HIT A TIRE, SURROUNDING A TIE-DOWN STAKE, & THE ACFT NOSED OVER.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAXI - FROM LANDING

**Findings** 

1. (C) CLEARANCE - MISJUDGED - PILOT IN COMMAND

-----

Occurrence #2: NOSE OVER

Phase of Operation: TAXI - FROM LANDING

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial; Flight instructor	Age:	43,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	July 6, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	5275 hours (Total, all aircraft), 510 hours (Total, this make and model), 5000 hours (Pilot In Command, all aircraft), 70 hours (Last 90 days, all aircraft), 10 hours (Last 24 hours, all aircraft)		

Page 2 of 5 MKC84LA066

## **Aircraft and Owner/Operator Information**

Aircraft Make:	PIPER	Registration:	N7843D
Model/Series:	PA-22-150 PA-22-150	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	22-5493
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1840 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	0-320
Registered Owner:	JAMES VONALLMEN	Rated Power:	150 Horsepower
Operator:	LLOYD R. DARTER	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

# Meteorological Information and Flight Plan

<u> </u>			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Unknown	Visibility	5 miles
Lowest Ceiling:	Overcast / 1500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	10°C
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	MOUNTAIN GROVE , MO (MO19)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	15:30 Local	Type of Airspace:	Class G

Page 3 of 5 MKC84LA066

## **Airport Information**

Airport:	RUSSELLVILLE MUNI M06	Runway Surface Type:	Grass/turf
Airport Elevation:	400 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	35.139423,-90.179878(est)

Page 4 of 5 MKC84LA066

#### **Administrative Information**

Investigator In Charge (IIC):	Roth, Eugene
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=33624

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MKC84LA066