



Aviation Investigation Final Report

Location: JASPER, Arkansas Accident Number: MKC84LA067

Date & Time: January 28, 1984, 10:10 Local Registration: N1681D

Aircraft: CESSNA 170B Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT LANDED THE ACFT ON PRIVATE PROPERTY TO VISIT RELATIVES. DURING THE LANDING THE ACFT GROUNDLOOPED AND COLLAPSED THE LEFT MAIN LANDING GEAR. THE PLT REPORTED THAT THE WINDS WERE FROM 290 DEGREES AT 18 KTS AND GUSTY. RUGGED TERRAIN SURROUNDED THE AREA OF LANDING.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (F) WEATHER CONDITION - GUSTS

3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

4. (C) GROUND LOOP/SWERVE - NOT CORRECTED - PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings
5. LANDING GEAR, MAIN GEAR ATTACHMENT - OVERLOAD

Page 2 of 5 MKC84LA067

Factual Information

Pilot Information

Certificate:	Private	Age:	24,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	November 30, 1982
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	300 hours (Total, all aircraft), 266 hours (Total, this make and model), 266 hours (Pilot In Command, all aircraft), 42 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N1681D
Model/Series:	170B 170B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	20323
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	July 22, 1983 Annual	Certified Max Gross Wt.:	2050 lbs
Time Since Last Inspection:	150 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2311 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	C-145-2
Registered Owner:	CLINT OWENS	Rated Power:	145 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MKC84LA067

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	HRO	Distance from Accident Site:	
Observation Time:	10:00 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 7000 ft AGL	Visibility	13 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	9°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	KANSAS CITY , MO (MKC)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	08:10 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:
Airport Elevation:		Runway Surface Condition:
Runway Used:	0	IFR Approach:
Runway Length/Width:		VFR Approach/Landing:

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	

Page 4 of 5 MKC84LA067

Administrative Information

Investigator In Charge (IIC):	Thorpe, Clint
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=33625

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MKC84LA067