

Aviation Investigation Final Report

Location:	PRATT, Kansas		Accident Number:	MKC85LA132
Date & Time:	June 15, 1985, 10:5	5 Local	Registration:	N6723C
Aircraft:	BEECH	C23	Aircraft Damage:	Substantial
Defining Event:	Injuries: 2 None		2 None	
Flight Conducted Under:	Part 91: General aviation - Instructional			

Analysis

STUDENT PILOT WAS ON HIS SECOND CROSS-COUNTRY FLIGHT TO THIS AIRPORT. HE STATED THAT AFTER TOUCHDOWN, HE REACHED TO RAISE THE FLAPS AND THE AIRPLANE STARTED TO DRIFT. HE OVERCORRECTED AND WENT OFF LEFT SIDE OF THE RUNWAY AND NOSED OVER WHEN HE WENT THROUGH A WASH.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings 1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING - ROLL

Findings 2. (F) TERRAIN CONDITION - DITCH

Factual Information

Pilot Information

Certificate:	Student	Age:	42.Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 31, 1984
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	33 hours (Total, all aircraft), 33 hour all aircraft), 17 hours (Last 90 days,	rs (Total, this make and model), 10 hou all aircraft)	urs (Pilot In Command,

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N6723C
Model/Series:	C23 C23	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	M-2369
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	October 3, 1984 Annual	Certified Max Gross Wt.:	2450 lbs
Time Since Last Inspection:	81 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	481 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-360-A4K
Registered Owner:	BEECH AIRCRAFT CORPORATION	Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night/dark
		-	3
Observation Facility, Elevation:	ICT ,1332 ft msl	Distance from Accident Site:	70 Nautical Miles
Observation Time:	10:50 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:	Scattered / 25000 ft AGL	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	26°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	WICHITA , KS (K31)	Type of Flight Plan Filed:	VFR
Destination:	PRATT , KS (PTT)	Type of Clearance:	None
Departure Time:	10:10 Local	Type of Airspace:	Class G

Airport Information

Airport:	PRATT MUNICIPAL PTT	Runway Surface Type:	Concrete
Airport Elevation:	1951 ft msl	Runway Surface Condition:	Dry
Runway Used:	35	IFR Approach:	None
Runway Length/Width:	6000 ft / 150 ft	VFR Approach/Landing:	Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	37.640724,-98.730926(est)

Administrative Information

Investigator In Charge (IIC):	Roth, Eugene	
Additional Participating Persons:	KATHLEEN I PERSON; WICHITA , KS	
Original Publish Date:		
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=33965	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.