





Aviation Investigation Final Report

Location: WESKAN, Kansas Accident Number: MKC85LA201

Date & Time: August 31, 1985, 18:15 Local Registration: N6903P

Aircraft: PIPER PA-24-250 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation

Analysis

THE PLT RPTD A HIGH ENG OIL TEMPERATURE & LOW OIL PRESSURE WHILE MANEUVERING OVER A SIESMIC OPERATION SITE IN WEST KANSAS. THE ACFT WAS SUBSTANTIALLY DAMAGED WHEN IT CONTACTED A DITCH DURING A FORCED LANDING. POST ACCIDENT INSPECTION FAILED TO DISCLOSE ANY MECHANICAL FAILURE/MALFUNCTION.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: MANEUVERING

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

- Findings
 2. TERRAIN CONDITION DIRT BANK/RISING EMBANKMENT
 3. DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND

Page 2 of 5 MKC85LA201

Factual Information

Pilot Information

Certificate:	Commercial	Age:	36,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 20, 1984
Occupational Pilot:	No Last Flight Review or Equivalent:		
Flight Time:	736 hours (Total, all aircraft), 207 hours (Total, this make and model), 615 hours (Pilot In Command, all aircraft), 76 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N6903P
	- · · - · ·		
Model/Series:	PA-24-250 PA-24-250	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	24-2037
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	July 29, 1985 Annual	Certified Max Gross Wt.:	2900 lbs
Time Since Last Inspection:	26 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3003 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	0-540
Registered Owner:	AVIATION ASSOCIATES	Rated Power:	250 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MKC85LA201

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	GDL ,3654 ft msl	Distance from Accident Site:	21 Nautical Miles
Observation Time:	17:51 Local	Direction from Accident Site:	10°
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	150°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	38°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	BOULDER , CO (1V5)	Type of Flight Plan Filed:	None
Destination:	CHEYENNE WELLS , CO (45V)	Type of Clearance:	None
Departure Time:	16:20 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	38.859634,-101.959869(est)

Page 4 of 5 MKC85LA201

Administrative Information

Investigator In Charge (IIC):	Thorpe, Clinton	
Additional Participating Persons:	ROBERT GLASCOCK; WICHITA , KS	
Original Publish Date:		
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=34020	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MKC85LA201