



Aviation Investigation Final Report

Location: BRINKLEY, Arkansas Accident Number: MKC90LA060

Date & Time: March 4, 1990, 15:30 Local Registration: N90061

Aircraft: CESSNA 140 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT SAID THAT WHILE ATTEMPTING TO LAND HIS NEWLY PURCHASED TAILWHEEL ACFT, HE HIT HARD, BOUNCED, THEN LANDED HARD AGAIN. THE LEFT MAIN GEAR WAS TORN OFF AND THE ACFT SPUN AROUND DAMAGING THE RIGHT WING. THE PLT HAD ACCUMULATED A TOTAL OF 11.5 HOURS IN THIS TYPE OF TAIL WHEEL ACFT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: RECOVERY FROM BOUNCED LANDING NOT PERFORMED AND PORPOISE ENCOUNTERED BY THE PILOT IN COMMAND.

Findings

Occurrence #1: HARD LANDING Phase of Operation: LANDING

Findings

- 1. (C) RECOVERY FROM BOUNCED LANDING NOT PERFORMED PILOT IN COMMAND
- 2. (C) PORPOISE/PILOT-INDUCED OSCILLATION ENCOUNTERED PILOT IN COMMAND
- 3. (F) LACK OF TOTAL EXPERIENCE IN TYPE OF AIRCRAFT PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED

Phase of Operation: LANDING

Findings
4. LANDING GEAR - OVERLOAD

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING

Page 2 of 5 MKC90LA060

Factual Information

Pilot Information

Certificate:	Private	Age:	54,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	May 19, 1989
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	579 hours (Total, all aircraft), 12 hours (Total, this make and model), 524 hours (Pilot In Command, all aircraft), 12 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N90061
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	9122
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated	Engine Model/Series:	C-85-12
Registered Owner:	EUGENEA FELKER	Rated Power:	85 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MKC90LA060

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	LIT ,258 ft msl	Distance from Accident Site:	50 Nautical Miles
Observation Time:	15:50 Local	Direction from Accident Site:	260°
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	CAMDEN , TN (OM4)	Type of Flight Plan Filed:	None
Destination:	(M36)	Type of Clearance:	None
Departure Time:	13:00 Local	Type of Airspace:	

Airport Information

Airport:	FEDERER M36	Runway Surface Type:	Asphalt
Airport Elevation:	194 ft msl	Runway Surface Condition:	Dry
Runway Used:	20	IFR Approach:	None
Runway Length/Width:	3000 ft / 50 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.880203,-91.179306(est)

Page 4 of 5 MKC90LA060

Administrative Information

Investigator In Charge (IIC): Hruban, John

Additional Participating Persons:

Original Publish Date: December 30, 1992

Last Revision Date:
Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=34937

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MKC90LA060