



# **Aviation Investigation Final Report**

Location: ALTHEIMER, Arkansas Accident Number: MKC90LA132

**Date & Time:** June 16, 1990, 14:30 Local **Registration:** N57706

Aircraft: PIPER PA-36-400 Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 137: Agricultural

### **Analysis**

WHILE ATTEMPTING TO LAND DOWN WIND ON A PRIVATE SOD STRIP, DURING AN AERIAL APPLICATION OPERATION, THE COMMERCIAL PILOT LOST DIRECTION CONTROL, GROUND-LOOPED, THEN VEERED OFF THE RUNWAY AND NOSED OVER. THE PILOT STATED THAT HE ATTEMPTED TO REGAIN CONTROL WITH BRAKING, BUT FELT THAT HE HAD NO BRAKES. INVESTIGATION FAILED TO REVEAL ANY BRAKE MALFUNCTION.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: DIRECTIONAL CONTROL WAS NOT MAINTAINED BY THE PILOT IN COMMAND. CONTRIBUTING FACTORS WERE LANDING WITH A TAILWIND. COMPENSATION FOR WIND CONDITIONS NOT CONSIDERED AND SELECTION OF THE WRONG RUNWAY.

#### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

#### **Findings**

1. (F) WEATHER CONDITION - TAILWIND

- 2. (F) COMPENSATION FOR WIND CONDITIONS NOT PERFORMED PILOT IN COMMAND
- 3. (F) WRONG RUNWAY SELECTED PILOT IN COMMAND
- 4. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND

-----

Occurrence #2: NOSE OVER Phase of Operation: LANDING - ROLL

Page 2 of 5 MKC90LA132

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial	Age:	20,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	March 26, 1990
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	926 hours (Total, all aircraft), 98 hours (Total, this make and model), 810 hours (Pilot In Command, all aircraft), 109 hours (Last 90 days, all aircraft), 83 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N57706
Model/Series:	PA-36-400 PA-36-400	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	36-7660032
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	4800 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	IO-720-A1B
Registered Owner:		Rated Power:	400 Horsepower
Operator:	AG AIR INC.	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MKC90LA132

**Meteorological Information and Flight Plan** 

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:00 Local	Type of Airspace:	

## **Airport Information**

Airport:	NONE	Runway Surface Type:	Grass/turf
Airport Elevation:	250 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.309722,-91.840545(est)

Page 4 of 5 MKC90LA132

#### **Administrative Information**

Investigator In Charge (IIC): Hruban, John

Additional Participating
Persons:

Original Publish Date: September 15, 1992

Last Revision Date:

Investigation Class: Class
Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=35002

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MKC90LA132