



Aviation Investigation Final Report

Location: GODDARD, Kansas Accident Number: MKC90LA137

Date & Time: June 26, 1990, 16:00 Local Registration: N1655C

Aircraft: CESSNA 180 Aircraft Damage: Substantial

Defining Event: 1 Minor, 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

WHILE ON FINAL APPROACH, AT ABOUT 350 FEET AGL, THE ENGINE FAILED. AN EMERGENCY LANDING WAS ATTEMPTED, SHORT OF THE RUNWAY, RESULTING IN A NOSE OVER IN A PLOWED FIELD. POST ACCIDENT INVESTIGATION REVEALED A LOOSE FUEL STRAINER SCREEN HAD TURNED SIDEWAYS IN THE LINE AND RESTRICTED THE FUEL FLOW.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FUEL STARVATION DUE TO A LOOSE FUEL STRAINER SCREEN. A FACTOR RELATED TO THIS ACCIDENT WAS LACK OF SUITABLE TERRAIN FOR A FORCED LANDING.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings

1. (C) FUEL SYSTEM, SCREEN - LOOSE

2. (C) FLUID, FUEL - STARVATION

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: NOSE OVER Phase of Operation: LANDING

Findings
3. (F) TERRAIN CONDITION - NONE SUITABLE

Page 2 of 5 MKC90LA137

Factual Information

Pilot Information

Certificate:	Private	Age:	51,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	February 12, 1990
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	3600 hours (Total, all aircraft), 2800 hours (Total, this make and model), 25 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N1655C
		_	
Model/Series:	180 180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	30355
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	5500 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	0-470-K
Registered Owner:	MARDIS, NICKY LEE	Rated Power:	230 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MKC90LA137

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ICT ,1332 ft msl	Distance from Accident Site:	6 Nautical Miles
Observation Time:	15:51 Local	Direction from Accident Site:	80°
Lowest Cloud Condition:	Clear	Visibility	12 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	11 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	36°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	CHEYENNE SPRING, CO (45V)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:15 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:
Airport Elevation:	1440 ft msl	Runway Surface Condition:
Runway Used:	0	IFR Approach: None
Runway Length/Width	•	VFR Approach/Landing: Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	37.650463,-97.569442(est)

Page 4 of 5 MKC90LA137

Administrative Information

Investigator In Charge (IIC):	Hruban, John
Additional Participating Persons:	MONTE DAVIS;
Original Publish Date:	November 9, 1992
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=35007

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MKC90LA137