



Aviation Investigation Final Report

Location: PLATTSBURGH, New York Accident Number: NYC83LA183

Date & Time: July 20, 1983, 14:00 Local Registration: N76079

Aircraft: CESSNA C140 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE ACFT GROUNDLOOPED FOLLOWING SEPARATION OF THE RIGHT WHEEL AND AXLE DURING A PRACTICE SHORT FIELD LANDING. EXAMINATION REVEALED TWO OF THE FOUR AXLE ATTACHING BOLTS WERE STRIPPED AND MISSING.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) LANDING GEAR, MAIN GEAR - SEPARATION

- 2. (F) DIRECTIONAL CONTROL NOT POSSIBLE PILOT IN COMMAND
- 3. (C) LANDING GEAR, AXLE SEPARATION
- 4. (F) DIRECTIONAL CONTROL NOT POSSIBLE PILOT IN COMMAND
- 5. (C) MAINTENANCE IMPROPER OTHER MAINTENANCE PERSONNEL

Occurrence #2: MAIN GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings 6. (C) LANDING GEAR, AXLE - STRIPPED THREAD

Page 2 of 6 NYC83LA183

Factual Information

Pilot Information

Certificate:	Commercial; Flight instructor; Private	Age:	Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 16, 1983
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1495 hours (Total, all aircraft), 50 hours (Total, this make and model), 1415 hours (Pilot In Command, all aircraft), 184 hours (Last 90 days, all aircraft)		

Page 3 of 6 NYC83LA183

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N76079
Model/Series:	C140 C140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	10473
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	January 31, 1983 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2300 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated	Engine Model/Series:	90
Registered Owner:	DRUCK & GERNER, DDS PC	Rated Power:	90 Horsepower
Operator:	BERNARD M. KENTILE	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	30 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	PLATTSBURGH (PLB)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:00 Local	Type of Airspace:	Class G

Page 4 of 6 NYC83LA183

Airport Information

Airport:		Runway Surface Type:	Grass/turf
Airport Elevation:	370 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	44.700908,-73.470169(est)

Page 5 of 6 NYC83LA183

Administrative Information

Investigator In Charge (IIC):	Taylor, Vernon
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=35234

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 NYC83LA183