



Aviation Investigation Final Report

Location: REHOBOTH BEACH, Delaware Accident Number: NYC84LA199

Date & Time: June 5, 1984, 11:40 Local Registration: N5870V

Aircraft: PIPER PA-32R Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

BASED ON ERRONEOUS INFORMATION PIC ASSUMED ROAD CONSTRUCTION WAS WORK TO PAVE GRASS STRIP. HE LANDED ON A ROAD BEING CONSTRUCTED IN A HOUSING EXPANSION AREA. DURING LANDING ROLL THE LEFT MAIN GEAR BROKE OFF AFTER CONTACTING A DIRT MOUND.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) TERRAIN CONDITION - ROUGH/UNEVEN

- 2. (C) IN-FLIGHT PLANNING/DECISION INADEQUATE PILOT IN COMMAND
- 3. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA NOT IDENTIFIED PILOT IN COMMAND
- 4. (C) LACK OF FAMILIARITY WITH GEOGRAPHIC AREA PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings 5. LANDING GEAR, MAIN GEAR - OVERLOAD

Page 2 of 6 NYC84LA199

Factual Information

Pilot Information

Certificate:	Commercial	Age:	67,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	October 28, 1983
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	2088 hours (Total, all aircraft), 14 hours (Total, this make and model), 1883 hours (Pilot In Command, all aircraft), 18 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 NYC84LA199

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N5870V
Model/Series:	PA-32R PA-32R	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	32R7780-370
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	July 28, 1983 Annual	Certified Max Gross Wt.:	3400 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1937 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-540-K1G5D
Registered Owner:	HAGERSTOWN REG. AERO CLUB	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

	9		
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	12 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	32°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	CHAMBERSBURG , PA (N68)	Type of Flight Plan Filed:	IFR
Destination:	REHOBOTH BEACH , PA (REH)	Type of Clearance:	None
Departure Time:	10:35 Local	Type of Airspace:	

Page 4 of 6 NYC84LA199

Airport Information

Airport:	REHOBOTH BEACH REH	Runway Surface Type:	Grass/turf
Airport Elevation:	28 ft msl	Runway Surface Condition:	Dry
Runway Used:	30	IFR Approach:	None
Runway Length/Width:	2790 ft / 150 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 5 of 6 NYC84LA199

Administrative Information

Investigator In Charge (IIC):	Taylor, Vernon
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=35675

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 NYC84LA199