



Aviation Investigation Final Report

Location: HOPEDALE, Massachusetts Accident Number: NYC88LA123

Date & Time: April 11, 1988, 12:30 Local Registration: N4695E

Aircraft: CESSNA 185 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT SAID HE FLARED TOO HIGH AND LANDED HARD. THE PILOT STATED THAT THE PROP CONTACTED THE GROUND, THE RIGHT LANDING GEAR BROKE, AND THE RT WING CONTACTED THE GROUND AND WAS BENT REARWARD DURING THE HARD LANDING. THE PLT DID NOT FILE AN ACC REPORT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) ALTITUDE - MISJUDGED - PILOT IN COMMAND 2. (C) FLARE - IMPROPER - PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings
3. (F) LANDING GEAR, MAIN GEAR - OVERLOAD

Page 2 of 5 NYC88LA123

Factual Information

Pilot Information

Certificate:	Private	Age:	39,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	November 17, 1986
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	142 hours (Total, all aircraft), 47 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N4695E
Model/Series:	185 185	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18503844
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	IO-520-D
Registered Owner:	JIM TOLSON	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 NYC88LA123

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)		Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:			Direction from Accident Site:	
Lowest Cloud Condition:	Unknown		Visibility	
Lowest Ceiling:	Unknown		Visibility (RVR):	
Wind Speed/Gusts:	/		Turbulence Type Forecast/Actual:	/
Wind Direction:	0°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:			Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:	No Obscurati	on; No Precipita	tion	
Departure Point:	NORWOOD	, MA (OWD)	Type of Flight Plan Filed:	None
Destination:	HOPEDALE	, MA (1B6)	Type of Clearance:	None
Departure Time:	00:00 Local		Type of Airspace:	Class G

Airport Information

Airport:	HOPEDALE-DRAPER 1B6	Runway Surface Type:	Asphalt
Airport Elevation:	269 ft msl	Runway Surface Condition:	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	3160 ft / 90 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 4 of 5 NYC88LA123

Administrative Information

Investigator In Charge (IIC): Hancock, Robert

Additional Participating
Persons:

Original Publish Date: December 3, 1989

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=36132

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 NYC88LA123