



Aviation Investigation Final Report

Location: FARMINGDALE, New Jersey Accident Number: NYC92LA125

Date & Time: June 13, 1992, 16:00 Local Registration: N17818

Aircraft: BEECH 33A Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT MADE A HARD LANDING, THE AIRPLANE BOUNCED COMING DOWN NOSE FIRST WHICH RESULTED IN THE NOSE GEAR COLLAPSING.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S IMPROPER RECOVERY FROM A BOUNCED LANDING WHICH RESULTED IN COLLAPSING OF THE NOSE GEAR. A FACTOR IN THE ACCIDENT WAS GUSTING CROSS WINDS.

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (F) WEATHER CONDITION - GUSTS

3. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND

4. (C) LANDING GEAR, NOSE GEAR - OVERLOAD

Factual Information

Pilot Information

Certificate:	Private	Age:	57,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 28, 1991
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1300 hours (Total, all aircraft), 624 hours (Total, this make and model), 1050 hours (Pilot In Command, all aircraft), 12 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Page 2 of 5 NYC92LA125

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N17818
Model/Series:	33A 33A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	CE710
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	December 29, 1991 Annual	Certified Max Gross Wt.:	3400 lbs
Time Since Last Inspection:	29 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2096 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO-520-BA
Registered Owner:	HGD AIRCRAFT INC	Rated Power:	285 Horsepower
Operator:	GERALD L. DORF	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

meteororogioai informati	<u> </u>			
Conditions at Accident Site:	Visual (VMC)		Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:			Direction from Accident Site:	
Lowest Cloud Condition:	Unknown		Visibility	7 miles
Lowest Ceiling:	Unknown		Visibility (RVR):	
Wind Speed/Gusts:	15 knots /		Turbulence Type Forecast/Actual:	/
Wind Direction:	290°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:			Temperature/Dew Point:	27°C
Precipitation and Obscuration:	No Obscuration	on; No Precipita	ation	
Departure Point:	FALMOUTH	, MA (5B6)	Type of Flight Plan Filed:	None
Destination:			Type of Clearance:	None
Departure Time:	14:30 Local		Type of Airspace:	Class D

Page 3 of 5 NYC92LA125

Airport Information

Airport:	ALLAIRE BLM	Runway Surface Type:	Asphalt
Airport Elevation:	159 ft msl	Runway Surface Condition:	Dry
Runway Used:	21	IFR Approach:	None
Runway Length/Width:	3700 ft / 50 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	

Page 4 of 5 NYC92LA125

Administrative Information

Investigator In Charge (IIC): Yurman, Alan

Additional Participating Persons:

Original Publish Date: August 26, 1993

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=37178

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 NYC92LA125