



Aviation Investigation Final Report

Location: IMNAHA, Oregon Accident Number: SEA84LA047

Date & Time: January 27, 1984, 11:30 Local Registration: N7771K

Aircraft: PIPER PA-20 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE ACFT NOSED OVER DURING A FORCED LANDING ON A SNOW COVERED FIELD. THE PLT REPORTED THAT THE ACFT BEGAN TO LOSE POWER AT ABOUT 6500 FT MSL. AN INSPECTION OF THE ENG DID NOT REVEAL ANY MECHANICAL MALFUNCTION OR DISCREPANCY.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: CRUISE - NORMAL

Findings

1. (F) FUEL SYSTEM, CARBURETOR - ICE

2. (C) CARBURETOR HEAT - IMPROPER USE OF - PILOT IN COMMAND

3. (F) WEATHER CONDITION - CARBURETOR ICING CONDITIONS

Occurrence #2: FORCED LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #3: NOSE OVER Phase of Operation: LANDING - ROLL

Page 2 of 5 SEA84LA047

Factual Information

Pilot Information

Certificate:	Private	Age:	33,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 16, 1983
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	125 hours (Total, all aircraft), 125 hours (Total, this make and model), 70 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N7771K
Model/Series:	PA-20 PA-20	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	20-605
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	May 1, 1983 Annual	Certified Max Gross Wt.:	1800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2876 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	O-290-D
Registered Owner:	JACK H. ROSS	Rated Power:	125 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 SEA84LA047

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	BKE ,3369 ft msl	Distance from Accident Site:	58 Nautical Miles
Observation Time:	11:53 Local	Direction from Accident Site:	210°
Lowest Cloud Condition:	Unknown	Visibility	30 miles
Lowest Ceiling:	Broken / 1500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	-2°C / -4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	PENDLETON , OR (PDT)	Type of Flight Plan Filed:	None
Destination:	LORDS FLAT , OR	Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Snow
Airport Elevation:		Runway Surface Condition:	Snow
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	45.459568,-116.749397(est)

Page 4 of 5 SEA84LA047

Administrative Information

Investigator In Charge (IIC):	Candace, Carrera
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=39869

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 SEA84LA047