



Aviation Investigation Final Report

Location: COALINGA, California Accident Number: SEA85LA191

Date & Time: May 19, 1985, 11:40 Local Registration: N6927P

Aircraft: PIPER PA-24-250 Aircraft Damage: Substantial

Defining Event: 5 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT MISTAKENLY LANDED ON A PVT AIRSTRIP AND DURING A X-WIND LANDING MADE A GO AROUND DUE TO A GUST OF WIND. THE ACFT STRUCK A DIRT BERM WITH THE RIGHT WING AND THE RIGHT MAIN GEAR.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING

Findings

1. (F) TERRAIN CONDITION - DIRT BANK/RISING EMBANKMENT

- 2. (F) LANDED AT WRONG AIRPORT LOW PILOT IN COMMAND
- 3. (F) WEATHER CONDITION CROSSWIND
- 4. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	49,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	450 hours (Total, all aircraft), 450 hours (Total, this make and model), 375 hours (Pilot In Command, all aircraft), 30 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N6927P
Model/Series:	PA-24-250 PA-24-250	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	24-2061
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	100 hour	Certified Max Gross Wt.:	2900 lbs
Time Since Last Inspection:	60 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4150 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-540-A1A5
Registered Owner:	JOHN JOSLIN	Rated Power:	250 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 SEA85LA191

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	30 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	LAS VEGAS , NV (LAS)	Type of Flight Plan Filed:	None
Destination:	COALINGA , CA	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	HARRIS AGROWEST	Runway Surface Type:	Asphalt
Airport Elevation:	30 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	3000 ft	VFR Approach/Landing:	Go around

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	4 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	5 None	Latitude, Longitude:	38.579833,-121.489631(est)

Page 3 of 4 SEA85LA191

Administrative Information

Investigator In Charge (IIC): Carrera, Candace

Additional Participating PAUL BIGLER; SACRAMENTO , CA
Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=40220

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 SEA85LA191