

Aviation Investigation Final Report

Location:	GRANTS PASS, Orego	on	Accident Number:	SEA87LA128
Date & Time:	April 3, 1987, 10:30 L	ocal	Registration:	N6901V
Aircraft:	MOONEY	M20F	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal			

Analysis

SHORTLY AFTER TAKEOFF THE PILOT REALIZED THAT HE HAD NO AIRSPEED INDICATION DUE TO HIS FORGETTING TO REMOVE THE PITOT COVER DURING PREFLIGHT. THE PILOT RETURNED TO LAND AT THE AIRPORT AND LANDED GEAR UP.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) PREFLIGHT PLANNING/PREPARATION - INADEQUATE - PILOT IN COMMAND

- 2. (C) MISC EQPT/FURNISHINGS NOT REMOVED
- 3. FLIGHT/NAV INSTRUMENTS, AIRSPEED INDICATOR INOPERATIVE

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings 4. (C) WHEELS UP LANDING - INADVERTENT - PILOT IN COMMAND 5. (F) ANXIETY/APPREHENSION - PILOT IN COMMAND6. (C) CHECKLIST - NOT USED - PILOT IN COMMAND7. (F) DIVERTED ATTENTION - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	53,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	November 3, 1986
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	343 hours (Total, all aircraft), 85 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	MOONEY	Registration:	N6901V
Model/Series:	M20F M20F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	221287
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	September 23, 1986 100 hour	Certified Max Gross Wt.:	2740 lbs
Time Since Last Inspection:	38 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1068 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-360
Registered Owner:	ROY C THOMPSON	Rated Power:	200 Horsepower
Operator:	ROY C. THOMPSON	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	40 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	16°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ition	
Departure Point:	GRANTS PASS , OR (3S8)	Type of Flight Plan Filed:	None
Destination:	MEDFORD , OR (MFR)	Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

Airport Information

Airport:	JOSEPHINE COUNTY 3S8	Runway Surface Type:	Asphalt
Airport Elevation:	1122 ft msl	Runway Surface Condition:	Dry
Runway Used:	30	IFR Approach:	None
Runway Length/Width:	4000 ft / 75 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	42.530052,-123.339973(est)

Administrative Information

Investigator In Charge (IIC):	Carrera, Candace		
Additional Participating Persons:	JOE BOGART; HILLSBORO , OR		
Original Publish Date:	November 8, 1988		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=40650		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.