



Aviation Investigation Final Report

Location: JEROME, Idaho Accident Number: SEA90LA105

Date & Time: June 21, 1990, 17:30 Local Registration: N4530N

Aircraft: AIR TRACTOR AT-401 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

DURING AN AERIAL APPLICATION FLIGHT, THE PILOT HAD COMPLETED ONE PASS OVER THE FIELD AND A TURN TO REVERSE DIRECTION WAS MADE WITH PARTIAL FLAPS EXTENDED. THE PILOT RETRACTED THE FLAPS AT A LOW ALTITUDE AND THE AIRPLANE SETTLED. AS IT SETTLED, THE AIRPLANE COLLIDED INTO A DRAINAGE EMBANKMENT. THE PILOT REPORTED THAT THERE WERE NO MECHANICAL FAILURES OR MALFUNCTIONS WITH THE AIRPLANE AT THE TIME OF THE ACCIDENT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT DID NOT MAINTAIN A PROPER ALTITUDE WHILE MANEUVERING TO REVERSE DIRECTION.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: MANEUVERING - TURN TO REVERSE DIRECTION

Findings

1. TERRAIN CONDITION - OPEN FIELD

2. (C) PROPER ALTITUDE - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	38,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 21, 1990
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	9000 hours (Total, all aircraft), 35 hours (Total, this make and model), 8900 hours (Pilot In Command, all aircraft), 195 hours (Last 90 days, all aircraft), 75 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Page 2 of 5 SEA90LA105

Aircraft and Owner/Operator Information

Aircraft Make:	AIR TRACTOR	Registration:	N4530N
Model/Series:	AT-401 AT-401	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	401-0762
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	6000 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	P&W
ELT:	Not installed	Engine Model/Series:	R-1340-AN1
Registered Owner:		Rated Power:	600 Horsepower
Operator:	WILLIAM M. WALTERS	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:	(U73)	Type of Clearance:	None
Departure Time:	17:15 Local	Type of Airspace:	

Page 3 of 5 SEA90LA105

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.730541,-114.430068(est)

Page 4 of 5 SEA90LA105

Administrative Information

Investigator In Charge (IIC): Eckrote, Debra

Additional Participating Persons:

Original Publish Date: December 15, 1992

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=41214

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 SEA90LA105