

Aviation Investigation Final Report

Location:	NAKNEK, Alaska		Accident Number:	ANC84LA115
Date & Time:	July 14, 1984, 14:30	Local	Registration:	N3910G
Aircraft:	CESSNA	U-206	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General avia	tion - Personal		

Analysis

THE ACFT NOSED OVER DURING A LANDING ON A SANDY BEACH. WITNESSES STATED, ACCORDING TO THE PLT, THAT THE NOSE WHEEL WAS COCKED 45 DEGREES TO THE RIGHT WHILE THE ACFT WAS ON THE FINAL APPROACH. UPON TOUCHDOWN THE ACFT VEERED TO THE RIGHT, THE NOSE GEAR COLLAPSED AND THE ACFT NOSED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: NOSE GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

1. (F) LANDING GEAR, NOSE GEAR ASSEMBLY - OVERLOAD

- 2. (F) TERRAIN CONDITION SOFT
- 3. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA SELECTED PILOT IN COMMAND
- 4. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND
- 5. (F) TERRAIN CONDITION SAND BAR
- 6. (C) GROUND LOOP/SWERVE UNCONTROLLED PILOT IN COMMAND

Occurrence #2: NOSE OVER Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Commercial	Age:	36.Male
Certificate.	Commercial	Aye.	50, Wale
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	February 16, 1984
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:		ours (Total, this make and model), 575 st 90 days, all aircraft), 1 hours (Last :	•

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N3910G
Model/Series:	U-206 U-206	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	U2060910
Landing Gear Type:	Tricycle	Seats:	6
Date/Type of Last Inspection:	September 11, 1983 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	40 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3600 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520F
Registered Owner:	STANLEY E. ALLEN	Rated Power:	300 Horsepower
Operator:	STANLEY E ALLEN	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 3000 ft AGL	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	KING SALMON , AK (AKN)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:15 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	58.799335,-156.900802(est)

Administrative Information

Investigator In Charge (IIC):	Kobelnyk, George
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4323

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.