



Aviation Investigation Final Report

Location: BURGRESS STRIP, Alaska Accident Number: ANC84LA143

Date & Time: August 13, 1984, 09:30 Local Registration: N3241D

Aircraft: CESSNA 180 Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT STATED THAT WHEN THE ACFT WAS ON SHORT FINAL APCH TO LAND ON AN AIRSTRIP, IT STALLED. DURING IMPACT, THE GEAR BOX, RIGHT WING TIP, PROP, ENG MOUNTS, ENG COWLING & RIGHT ELEVATOR WERE DAMAGED. THE PLT RECOMMENDED RECEIVING TRAINING BEFORE ATTEMPTING OFF ARPT OPERATIONS OR MOUNTAIN FLYING. ALSO, HE RECOMMENDED BEING AWARE OF OPTICAL ILLUSIONS BEFORE TRYING TO LAND ON SIDE-HILL STRIPS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

- 1. (F) PLANNED APPROACH MISJUDGED PILOT IN COMMAND
- 2. (C) AIRSPEED NOT MAINTAINED PILOT IN COMMAND
- 3. (C) FLARE IMPROPER PILOT IN COMMAND
- 4. (F) LACK OF FAMILIARITY WITH GEOGRAPHIC AREA PILOT IN COMMAND
- 5. (F) LACK OF TOTAL EXPERIENCE IN TYPE OPERATION PILOT IN COMMAND

Page 2 of 6 ANC84LA143

Factual Information

Pilot Information

Certificate:	Private	Age:	42,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	December 5, 1983
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	170 hours (Total, all aircraft), 18 hours (Total, this make and model), 150 hours (Pilot In Command, all aircraft), 18 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC84LA143

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N3241D
Model/Series:	180 180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	32039
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	September 8, 1983 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:	17 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	17 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-470
Registered Owner:	CARL O'CONNOR	Rated Power:	230 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Meteorological illionilati	on and ingite ian		
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	60 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	9°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipi	tation	
Departure Point:	BRADY SKYRANCH , AK	Type of Flight Plan Filed:	Unknown
Destination:		Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 4 of 6 ANC84LA143

Airport Information

Airport:	BURGESS STRIP	Runway Surface Type:	Gravel
Airport Elevation:	900 ft msl	Runway Surface Condition:	Dry
Runway Used:	35	IFR Approach:	None
Runway Length/Width:	1000 ft / 40 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	

Page 5 of 6 ANC84LA143

Administrative Information

Investigator In Charge (IIC):	Michelangelo, James
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4342

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC84LA143