



Aviation Investigation Final Report

Location:	ANCHORAGE, Alaska	Accident Number:	ANC84LA168
Date & Time:	August 31, 1984, 15:30 Local	Registration:	N65064
Aircraft:	CESSNA ECTOR 305A	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

LANDING AREA SELECTED BY PLT WAS SLICK DUE TO MUD FROM RECENT TIDAL WATERS. ACFT SLID ON TOUCHDOWN AND PLT WAS UNABLE TO STOP. APPLIED FULL PWR IN ATTEMPT TO CLEAR A GULLY AT END OF LANDING AREA. MAIN GEAR CONTACTED FAR EDGE OF GULLY AND ACFT NOSED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: OVERRUN
Phase of Operation: LANDING - ROLL

Findings

1. (C) IN-FLIGHT PLANNING/DECISION - IMPROPER - PILOT IN COMMAND
2. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION - WET
3. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - SELECTED - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: LANDING

Findings

- 4. REMEDIAL ACTION - DELAYED - PILOT IN COMMAND
- 5. CLEARANCE - NOT OBTAINED - PILOT IN COMMAND

Occurrence #3: NOSE OVER
Phase of Operation: LANDING

Factual Information

Pilot Information

Certificate:	Commercial	Age:	36, Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--w/ waivers/lim	Last FAA Medical Exam:	August 30, 1984
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	2500 hours (Total, all aircraft), 500 hours (Total, this make and model), 50 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA ECTOR	Registration:	N65064
Model/Series:	305A 305A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2031
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	May 20, 1984 Annual	Certified Max Gross Wt.:	2100 lbs
Time Since Last Inspection:	50 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	500 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	O-470-11
Registered Owner:	RICK R. MARTIN	Rated Power:	230 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:	15:00 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	90 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	18°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	ANCHORAGE , AK (Z41)	Type of Flight Plan Filed:	None
Destination:	CHICKALOON FLAT, AK	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Airport Information

Airport:	ANCHORAGE INTERNATIONAL ANC	Runway Surface Type:	
Airport Elevation:	10 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	61.159069,-149.990112(est)

Administrative Information

Investigator In Charge (IIC): Kobelnyk, George

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=4365>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).